



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS3/LPC20013711/Aqd3e2-1	
			Date: 23/03/2021	
			Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
	Insured Veh.	SDQ 407Z	Veh. Inspected	SJN 9965P
	Policy No.	Z20VP05026342	Coverage (\$)	0.00
	Claim No.	20/20/20/VP05/023991	Excess (\$)	0.00
	Assign From	ONG LI LI	Assign Date	17/03/2021
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA WISH	c.c	1794
	Engine No.	HIDDEN	Year of Reg.	2009
	Chassis No.	JTDER12W303002116	Colour	SILVER
	Odometer	338544 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	MICHELIN	6 mm
	L/H Front Tyre	195/65 R15	MICHELIN	6 mm
	R/H Rear Tyre	195/65 R15	MICHELIN	6 mm
	L/H Rear Tyre	195/65 R15	MICHELIN	6 mm
4. Description of Damages				
	THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.			
5. General Information				
	Accident Date	08/12/2020	Inspection Date	19/03/2021
	Survey held at	SIN HOCK LEE MOTOR REPAIR 51 UBI AVENUE 1 #01-09 PAYA UBI INDUSTRIAL PARK . SINGAPORE 408933		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		13 Working Days	