



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD	Ref: CS3/AIG21003516/Eqf3
78 SHENTON WAY #09-16	Date: 18/03/2021
AIG BUILDING	
SINGAPORE 079120	Code: AIG

#### 1. Policy Particulars :- (THIRD PARTY CLAIM)

<b>Insured Veh.</b>	SGN 3136R	<b>Veh. Inspected</b>	SLL 6826P
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>		<b>Excess (\$)</b>	0.00
<b>Assign From</b>	DIVYASHNI SUBRAMANIAM	<b>Assign Date</b>	18/03/2021

#### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>		<b>c.c</b>	0
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	
<b>Chassis No.</b>		<b>Colour</b>	
<b>Odometer</b>	-	<b>Steering</b>	
<b>Brakes</b>		<b>Modification</b>	
<b>General</b>			

#### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>			mm
<b>L/H Front Tyre</b>			mm
<b>R/H Rear Tyre</b>			mm
<b>L/H Rear Tyre</b>			mm

#### 4. Description of Damages

--

#### 5. General Information

<b>Accident Date</b>	16/03/2021	<b>Inspection Date</b>	20/04/2021
<b>Survey held at</b>	25 Kaki Bukit Road 4 #06-46 Synergy@KB		
<b>Repairer</b>	TRIPLE-T AUTOMOBILE		

#### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
 B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
 THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.  
 C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.