

Section A - Accident Details

Registration Number	SHB5136D
Case Reference Number	TAX/03/21/2055
Registration Date	1/11/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	CHUA KAY HWEE
Type of Accident	Head to Rear
Accident Date and Time	17/3/2021 12:00 PM
Accident Reported Date and Time	17/3/2021 4:39 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24110114
Special Instruction to ARC, if any	TP / RER RIGHT PORTION /SOMPO
Prepared Date and Time	18/3/2021 9:56 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,095.00	\$550.00
Total Spray Cost	\$2,934.00	\$680.00
Total Spare Part Cost	\$7,573.06	\$1,468.98
Total Other Cost	\$700.00	\$80.00
TOTAL COST	\$12,302.06	\$2,778.98
Lump Sum Total	\$12,300.00	\$2,800.00 (L/S)
Number of Repair Days	7.0	4.0
Prepared / Adjusted By	Ang Bang Kien	Sun Pin (LKK) / Sompo
ARC / Surveyor Sign Off Date	22/03/2021 5:37 PM	22/03/2021 11:29 AM
Signature		
Remarks	Total number of repair days = 4 days. SUP = + 1 day.	L./S. After paint photo.



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 08/04/2021

User ID PohSuan

Section C - Quotation and Accident Invoice Details			
Quotation Number	QN-2104-0052	Invoice Number	
Quotation Date	08.04.2021	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates		
Part 1 - Labour Works		
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION RH	\$845.00	\$400.00 /
TO REPAIR REAR END PANEL	\$250.00	\$150.00 / Supp
Total Labour	\$1,095.00	\$550.00

Part 2 - Spray Painting & Panel Beating Related Works		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00 /
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY FILLER RR BUMPER LH	\$180.00	\$0.00
TO RESPRAY FILLER RR BUMPER RH	\$180.00	\$80.00 /
TO RESPRAY REAR FENDER RH	\$378.00	\$200.00 /
TO RESPRAY REAR DOOR RH	\$378.00	\$0.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$100.00 /
TO RESPRAY REAR SPOILER	\$180.00	\$0.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
TO RESPRAY REAR SPARE TYRE PANEL	\$180.00	\$0.00
TO RESPRAY RIM	\$180.00	\$0.00
TO RESPRAY REAR FLOOR SIDE PANEL RH	\$180.00	\$0.00
TO RESPRAY REAR PANEL	\$180.00	\$100.00 / Supp
Total Spray Painting & Panel Beating	\$2,934.00	\$680.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$30.00 /
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$30.00 /
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00 /
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$700.00	\$80.00

Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		69211470	DOOR OUTER HANDLE REAR, RH	0.00	\$93.90	0.00	\$0.00	Replace	Not Given X
		21A1	EXTENSION, REAR FLOOR SIDE PANEL, RH	0.00	\$76.20	0.00	\$0.00	Replace	Not Given X
		58315470	SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Not Given X
		20							

} SVC



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 06/04/2021

User ID PohSuan

Part No	Description	Qty	Unit Price	Disc	Net Price	Est Price	Work	Material
5831147130	SPARE TYRE PANEL , PAN, REAR FLOOR	0.00	\$564.80	0.00	\$0.00	\$0.00	Replace	Not Given X
5830747090	END PANEL SUB-ASSY, BODY LOWER BACK	0.00	\$629.80	0.00	\$0.00	\$0.00	Replace	Check X
	STICKER DECAL 6555 8888	1.00	\$21.60	0.00	\$21.60	\$21.60	Replace	Replace ✓
	SMRT LOGO	1.00	\$7.80	0.00	\$7.80	\$7.80	Replace	Replace ✓
7608547916	SPOILER SUB-ASSY, REAR	0.00	\$1,322.10	0.00	\$0.00	\$0.00	Replace	Not Given X
7540348010	EMBLEM SUB-ASSY REAR	1.00	\$46.30	25.00	\$34.73	\$34.73	Replace	Replace ✓
7544247130	NAME PLATE (PRIUS) , LUGGAGE COMPARTMENT	1.00	\$52.30	25.00	\$39.23	\$39.23	Replace	Replace ✓
7544147090	NAME PLATE (HYBRID) , LUGGAGE COMPARTMENT	1.00	\$52.30	25.00	\$39.23	\$39.23	Replace	Replace ✓
7680147110A1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-TYRE	1.00	\$891.20	100.00	\$0.00	\$0.00	Replace	Repair ✓
		0.00	\$126.74	0.00	\$0.00	\$0.00	Replace	Not Given X
4261147450	WHEEL, DISC	0.00	\$1,555.10	0.00	\$0.00	\$0.00	Replace	Not Given X
6563747060	LINER, REAR FENDER , RH	0.00	\$135.80	0.00	\$0.00	\$0.00	Replace	Check X
6556547010	PATCH, SIDE PANEL REAR END , RH & LH	0.00	\$33.70	0.00	\$0.00	\$0.00	Replace	Check X
6160147150	PANEL SUB-ASSY, FENDER REAR RH	1.00	\$824.80	100.00	\$0.00	\$0.00	Replace	Repair ✓
6863047050	CHECK ASSY, REAR DOOR	0.00	\$153.50	0.00	\$0.00	\$0.00	Replace	Not Given X
6877052031	HINGE ASSY, REAR DOOR , LOWER RH	0.00	\$73.30	0.00	\$0.00	\$0.00	Replace	Not Given X
6875020122	HINGE ASSY, REAR DOOR , UPPER RH	0.00	\$83.30	0.00	\$0.00	\$0.00	Replace	Not Given X
6700347210	PANEL SUB-ASSY, REAR DOOR , RH	0.00	\$1,243.90	0.00	\$0.00	\$0.00	Replace	Not Given X
5839847050	COVER, REAR FLOOR UNDER , RH	0.00	\$169.50	0.00	\$0.00	\$0.00	Replace	Check X
6625947010	COVER, REAR FLOOR UNDER CENTER	0.00	\$222.60	0.00	\$0.00	\$0.00	Replace	Check X
5839947030	COVER, REAR FLOOR UNDER , LH	0.00	\$234.30	0.00	\$0.00	\$0.00	Replace	Not Given X
8149747020	COVER, REAR COMBINATION LAMP, RH	0.00	\$54.00	0.00	\$0.00	\$0.00	Replace	Check X
8158147010	LENS & BODY ASSY , RR BUMPER , RH	1.00	\$486.80	10.00	\$438.12	\$438.12	Replace	Replace ✓
8155147281	LENS & BODY, REAR COMBINATION LAMP , RH	0.00	\$438.10	0.00	\$0.00	\$0.00	Replace	Check X
8999730100	ANTENNA, ELECTRICAL KEY	0.00	\$60.30	0.00	\$0.00	\$0.00	Replace	Not Given X
	SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	\$0.00	Replace	Check X
	PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	\$120.00	Replace	Replace ✓
5216947020	COVER, GUARD RR BUMPER LOWER	1.00	\$14.80	25.00	\$11.10	\$11.10	Replace	Replace ✓
5256647900	FILLER, RR BUMPER , LH	0.00	\$119.90	0.00	\$0.00	\$0.00	Replace	Not Given X
5256547900	FILLER, RR BUMPER , RH	1.00	\$119.90	100.00	\$0.00	\$0.00	Replace	Repair ✓
5216116010	GUARD, RR BUMPER, LOWER	1.00	\$558.30	25.00	\$418.73	\$418.73	Replace	Replace ✓
5216116010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$1.50	25.00	\$11.25	\$11.25	Replace	Replace ✓
5259147050	SEAL, RR BUMPER , RH	0.00	\$85.20	0.00	\$0.00	\$0.00	Replace	Check X
5257647040	RETAINER, RR BUMPER, LH	0.00	\$111.50	0.00	\$0.00	\$0.00	Replace	Not Given X
5257547040	RETAINER, RR BUMPER, RH	1.00	\$112.70	25.00	\$84.53	\$84.53	Replace	Replace ✓
5246147010	PAD, RR BUMPER, CTR	3.00	\$2.20	25.00	\$4.95	\$4.95	Replace	Replace ✓
5246247010	PAD, RR BUMPER, RH & LH , 3	2.00	\$3.80	25.00	\$5.70	\$5.70	Replace	Replace ✓
5246247020	PAD, RR BUMPER, RH & LH , 2	2.00	\$3.80	25.00	\$5.70	\$5.70	Replace	Replace ✓
5246247030	PAD, RR BUMPER, RH & LH , 1	2.00	\$3.80	25.00	\$5.70	\$5.70	Replace	Replace ✓
5202347030	REAR BUMPER REINFORCEMENT	0.00	\$318.80	0.00	\$0.00	\$0.00	Replace	Check X
5215947913	COVER, RR BUMPER ASSY	1.00	\$423.90	25.00	\$317.93	\$317.93	Replace	Replace ✓
Total			\$11,811.14		\$1,566.30			

SVC
SVC
Nec
Nec
SVC
Nec
Nec
Nec
R
SVC
SVC
R
SVC
SVC
SVC
SCR
SVC
Nec
Mis
SVC
R
CRU
Nec
SVC
SVC
BR
Nec
Nec
Nec
SVC
CRU



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 06/04/2021
 User ID : PohSuan

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		5256547900	FILLER, RR BUMPER , RH	1.00	\$119.90	25.00	\$89.93	Replace	Replace
			SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	Replace
Total					299.90		269.93		

cut short

1836.23 /

- 20%

+ 1468.98 /

+ 550.00 /

+ 760.00 /

2778.98 /

45 \$ 2800 /

4 days

SHB 5136P