



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFY 3880D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	RR BUMPER LH MOUNT (SN)	SERVICEABLE	198.30	-
1	RR BUMPER RH MOUNT (SN)	SERVICEABLE	198.30	-
1	RR BUMPER LOWER TRIM (PRIMED) (SN)	DEFORMED	224.45	224.45
1	RR BUMPER CTR GUIDE (SN)	DEFORMED	51.50	51.50
1	ADAPTER (SN)	DEFORMED	81.00	81.00
1	RR BUMPER CARRIER (SN)	BENT	800.80	800.80
1	RR BUMPER PANEL PRIMED (SN)	DEFORMED	1,496.35	1,496.35
1	COVER TOW FITTING REAR PRIMED (SN)	SERVICEABLE	50.65	-
1	MODEL LETTERING 740LI (SN)	NECESSARY	62.55	62.55
4	DECOUPLING RING PDC TORQUE CONVERTE (SN)	NOT NECESSARY	20.20	-
2	BUMPER PDC SENSOR (A90 SOPHISTOGRAU) (SN)	SERVICEABLE	737.60	-
1	RR BUMPER PROTECTIVE RUBBER STRIP C (SN)	CUT	103.85	103.85
1	RR CENTRE COVERING (SN)	DEFORMED	191.85	191.85
2	EXPANDING NUT (SN)	NECESSARY	2.00	2.00
1	BMW EMBLEM (SN)	NECESSARY	69.50	69.50
2	EMBLEM GROMMET (SN)	NECESSARY	1.60	1.60
4	PLUG (SN)	NECESSARY	4.20	4.20
10	PLUG BLACK D=5MM (SN)	NECESSARY	9.00	9.00
1	SUNDRIES (SN)	NECESSARY	80.00	80.00
1	BOOTLID (SN)	BENT	1,987.90	1,987.90
			6,371.60	5,166.55
<u>LABOUR</u>				
	TO REPLACE REAR BOOT LID ,REAR BUMPER AND ATTACHMENT ETC.INCLUDING TO REMOVE AND INSTALL BODY PARTS IN ORDER TO CARRY OUT PAINTING JOB AND MADE GOOD ON TAIL END PANE.		2,125.00	2,125.00
	TO RESPRAY REAR BUMPER ,TAIL END PANEL AND REAR BOOT LID .		2,536.00	2,536.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION .		150.00	150.00
			4,811.00	4,811.00
GRAND TOTAL			11,182.60	9,977.55
RECOMMENDED COST OF REPAIRS				9,977.55

Report Ref No. CC4/ASM18005301/T1ps3q2-1

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.