

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190527 (AfterSales)
63190533/530 (Motorrad)
Fax 64796601 (AfterSales)
64796624 (Motorrad)

SERVICE TAX INVOICE

RE-PRINT

Repair Order No. : b1 1253266	Page No. : 1 of 2
Date IN : 23/03/2018	Invoice Number : 1952684 / WSB
Cust. Svc. Advisor : Merina Chia San San	Invoice Date : 09/04/2018
	Payment Term : Cash
	Invoice By : Teng Wai Khan

- CUSTOMER INFORMATION - Kam You Kin (Gan YaoJian) 2L Limau Garden Singapore 465921	- INVOICE TO - 40000 Cash Sales - Service Singapore
--	--

REGN. NO. SFY3880D	CHASSIS NO. DD87413	REGN. DATE 16/07/2014	MODEL 740LiA	MILEAGE 41694
------------------------------	-------------------------------	---------------------------------	------------------------	-------------------------

<u>CODE</u>	<u>DESCRIPTION</u>	<u>UNITS</u>	<u>NETT</u>
	To replace rear boot lid, rear bumper and attachments etc	1.00	2,125.00
	including to remove and install body parts in order to carry out painting job And made good on tail end pane		
	To respray rear bumper, tail end panel and rear boot lid.	1.00	2,536.00
61013	To check electrical wiring systems and lightings at the rear section for proper function.	1.00	150.00
ps	Sundries.	1.00	80.00
	ACCIDENT REPAIR. DATE OF ACCIDENT : 20.3.2018	0.00	0.00
	VEHICLE WAS SURVEYED BY MR TAUFIKH FROM LKK AUTO CONSULTANTS PTE LTD ON 21.3.2018 AT 4.00 PM.		
Sub-Total :			4,891.00

BMW Dealer

Performance Motors LimitedA member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

21 MAR 2018

Estimate No. : b1 46315 Page No. : 1 of 2
 Date Estimated : 21/03/2018
 Prepared By : Merina Chia San San

- ESTIMATE REPAIR FOR -Kam You Kin (Gan YaoJian)
2L Limau Garden

Singapore 465921

- ACCOUNT - 40000Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFY3880D	DD87413	16/07/2014	740LiA	0

DESCRIPTION	VALUE
To replace rear bumper including attachments etc and to knock out dented area caused by accident	1700 2,550.00
To paint rear bumper and bootlid	1068 2,076.00
To check electrical wiring systems and lightings at the rear section for proper function.	150 177.00
To remove and install boot compartment carpet and garnish to facilitate repairs.	270 271.00
Sundries	? 80.00

Total Labour 1: 5,154.00

DESCRIPTION	QTY	PRIC	VALUE	
RR BUMPER LH MOUNT	1	198.30	X 198.30	SVC
RR BUMPER RH MOUNT	1	198.30	X 198.30	SVC
RR BUMPER LOWER TRIM (PRIMED)	1	224.45	de 224.45	✓
RR BUMPER CTR GUIDE	1	51.50	de 51.50	✓
ADAPTER	1	81.00	de 81.00	✓
RR BUMPER CARRIER	1	800.80	bt 800.80	✓
RR BUMPER PANEL PRIMED	1	1,496.35	de 1,496.35	✓
COVER TOW FITTING REAR PRIMED	1	50.65	X 50.65	SVC
MODEL LETTERING 740LI	1	62.55	nn 62.55	✓
DECOUPLING RING PDC TORQUE CONVERTE	4	5.05	nn 20.20	X
BUMPER PDC SENSOR (A90 SOPHISTOGRAU	2	368.80	? X 737.60	SVC

Total Parts : 3,921.70

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 46315
Date Estimated : 21/03/2018
Prepared By : Merina Chia San San

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFY3880D	DD87413	16/07/2014	740LiA	0

Supp

51127301239	RR BUMPER PROTECTIVE RUBBER STRIP C	1.00	cut	103.85	✓
51757187958	RR CENTRE COVERING	1.00	de	191.85	✓
51127020321	EXPANDING NUT	2.00	nec	2.00	✓
KK Auto Consultants hence notif					
51148132375	BMW EMBLEM	1.00	nec	69.50	✓
51141807495	EMBLEM GROMMET	2.00	nec	1.60	✓
51471911992	PLUG	4.00	nec	4.20	✓
52208133466	PLUG BLACK D=5MM	10.00	nec	9.00	✓
41627172332	BOOTLID	1.00	bt	1,987.90	✓

Acknowledged by Repairer
Signature:
Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement	
Regn No. _____	Claim No. _____
Date & Time <u>21/3/18</u>	Excess S\$ _____
Surveyor's Name <u>Tan Jiah</u>	Sign <u>[Signature]</u>
Surveyor's Tel <u>97495749</u>	Authorised Yes / No _____
Authorised Date <u>WP</u>	Time _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____	
Surveyor's E-mail <u>tanjiah@chando.com</u>	
No. of Working Days Recommend <u>5 days</u>	

Labour 1	:	5,154.00
Parts	:	3,921.70
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	635.30
Grand Total	:	9,711.00

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **