

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

Estimate No. : **b1 57849**
Date Estimated : **17/03/2021**
Prepared By : **Brandon Chan Eng Meng**

- ESTIMATE REPAIR FOR -
Danny Chan Chia Aun (Chen Jia'an)
55 Mimosa View

- ACCOUNT - 135
China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

Singapore 805635

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKN8824H	WBA3A16070NS375	25/07/2014	316iA/4	139249

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace rear bumper panel, rear trunk lid and attachment parts.	1,700.00	0.00	1,700.00	
To spray paint rear bumper & rear trunk.	1,826.00	0.00	1,826.00	
To check electrical wiring system and lighting at the rear section.	168.00	0.00	168.00	
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.	168.00	0.00	168.00	
To transfer lock mechanism from old to new bootlid including conduct check on new bootlid central locking system for proper function.	504.00	0.00	504.00	
To carry out body cavity preservation. (Per panel).	100.00	0.00	100.00	
Sundries	80.00	0.00	80.00	
DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
BOOTLID	1,241.10	1.00	0.00	1,241.10
REAR BUMPER CENTRE GUIDE	56.05	1.00	0.00	56.05
REAR BUMPER PANEL PRIMED BASIS	1,184.75	1.00	0.00	1,184.75
REAR PDC HOLDER SET	25.75	1.00	0.00	25.75
GROMMET	0.80	2.00	0.00	1.60
PLAQUE 74MM	71.95	1.00	0.00	71.95
TRUNK LID LOCK	219.30	1.00	0.00	219.30
RR BUMPER LH REFLECTOR	37.90	1.00	0.00	37.90
REAR LH LIGHT IN TRUNK LID	274.40	1.00	0.00	274.40
(DG/SL) ADHESIVE SET K6	53.05	1.00	0.00	53.05
SUPPLEMENTARY ITEMS				
Total Labour :				4,546.00
Total Parts :				3,165.85
Total Labour & Parts :				7,711.85
Deduction for Excess :				
Total Repair Costs less Excess:				7,711.85

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

GST @7%:	539.83
Grand Total :	<u>8,251.68</u>

CAR RENTAL=\$428.00
GIA SEARCH FEE=\$2.00

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



supplementary

Estimate No. : **b1 57849**
Date Estimated : **17/03/2021**
Prepared By : **Brandon Chan Eng Meng**

- ESTIMATE REPAIR FOR -
Danny Chan Chia Aun (Chen Jia'an)
55 Mimosa View

Singapore 805635

- ACCOUNT - 135
China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKN8824H	WBA3A16070NS375	25/07/2014	316iA/4	139249

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# GROMMET	0.80	2.00	0.00	1.60
# TRUNK LID LOCK	219.30	1.00	0.00	219.30
# SUPPLEMENTARY ITEMS				
Total Labour :				
Total Parts :				220.90