

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : ONG SOCK HOON LENA
58 DA SILVA LANE

SINGAPORE 549785
TEL: 93837726
ATTN:

Estimate No: MC1901824
Date: 16 Mar 2021
Policy No: MT/00797068
Veh Reg No: SGU8845H
Make/Model: DAIHATSU MATERIA
1.5 A ABS

Your Ref No: SGU8845H
Claim Type: Third Party
Accident Date: 14/03/2021
TP Veh Reg No: SGG1889B

Not Notified
Clay &
Meowing After Paint
6 days

Estimate Repair Cost to Vehicle No :SGU8845H

Description	Quantity	List Price	Amount
		S\$	S\$
SPARE PARTS			
1 REAR WINDSCREEN MOULDING TOP - CHECK PRICE	1 PC	na 0.00 X	
2 REAR WINDSCREEN MOULDING LH &RH - CHECK PRICE	1 PC	na 0.00 X	
3 REAR WINDSCREEN MOULDING BTM - CHECK PRICE	1 PC	na 0.00 X	
4 TAILAMP LH - CHECK PRICE	1 PC	na 0.00 X	
5 TAILAMP PANEL LH - CHECK PRICE	1 PC	na 0.00 X	
6 TAILAMP LOWER BEAM LH - CHECK PRICE	1 PC	na 0.00 X	
7 REAR BUMPER - CHECK PRICE	1 PC	na 0.00 X	
8 REAR BUMPER SIDE RETAINER LH - CHECK PRICE	1 PC	na 0.00 X	
9 REAR BUMPER CLIPS - CHECK PRICE	12 PC	na 0.00 X	
10 REAR FENDER LH - CHECK PRICE	1 PC	na 0.00 X	
11 REAR FENDER COWLING LH - CHECK PRICE	1 PC	na 0.00 X	
12 REAR FENDER COWLING CLIPS - CHECK PRICE	8 PC	na 0.00 X	
13 SIDE SKIRT LH - CHECK PRICE	1 PC	na 0.00 X	
14 REAR DOOR LH - CHECK PRICE	1 PC	na 0.00 X	
15 REAR DOOR RUBBER (AT DOOR) LH - CHECK PRICE	1 PC	na 0.00 X	
16 REAR DOOR INNER LOCK LH - CHECK PRICE	1 PC	na 0.00 X	
17 FRONT DOOR LH - CHECK PRICE	1 PC	na 0.00 X	
18 FRONT DOOR RUBBER (AT DOOR) LH - CHECK PRICE	1 PC	na 0.00 X	
19 FRONT DOOR OUTER HANDLE LH - CHECK PRICE	1 PC	na 0.00 X	
20 FRONT DOOR OUTER HANDLE COVER LH - CHECK PRICE	1 PC	na 0.00 X	
21 FRONT DOOR INNER LOCK LH - CHECK PRICE	1 PC	na 0.00 X	
		0.00	0.00
Special Nett			
22 INNER SEAL	1 PC	na 20.00 X	
23 WINDSCREEN SEALANT	1 PC	na 40.00 X	
24 SPORT RIM LHR - CHECK PRICE	1 PC	na 0.00 X	
25 TYRE LHR - CHECK PRICE	1 PC	na 0.00 X	
		60.00	60.00
LABOUR			
26 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	201
27 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN.	1 PC	na 120.00 X	
28 TO DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM SUCH AS POWER WINDOW MOTOR AND REGULATOR TO NEW DOOR/FACILITATE REPAIR	1 PC	120.00	601



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : ONG SOCK HOON LENA
58 DA SILVA LANE

SINGAPORE 549785

TEL: 93837726

ATTN:

Estimate No: MC1901824

Date: 16 Mar 2021

Policy No: MT/00797068

Veh Reg No: SGU8845H

Make/Model: DAIHATSU MATERIA
1.5 A ABS

Your Ref No: SGU8845H

Claim Type: Third Party

Accident Date: 14/03/2021

TP Veh Reg No: SGG1889B

Estimate Repair Cost to Vehicle No :SGU8845H

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
29 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	1 PC	180.00	180.00
30 TO REMOVE AND REINSTALL/REPLACE FUEL TANK, FIXTURE AND ATTACHMENTS.	1 PC	60.00	60.00
31 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	60.00	60.00
32 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	60.00	60.00
33 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD RR FENDER LH.TO KNOCK & REPAIR ROCKER PANEL INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	850.00	850.00
34 TO SPRAY REAR BUMPER,REAR FENDER LH,REAR DOOR LH,FRONT DOOR LH,SIDE SKIRT LH.	1 PC	1,000.00	1,000.00
		2,490.00	2,490.00

Total S\$ 2,550.00

Add GST @ 7% 178.50

Total Amount Payable S\$ 2,728.50

TOTAL: SINGAPORE DOLLAR TWO THOUSAND SEVEN HUNDRED TWENTY EIGHT AND CENTS FIFTY ONLY

Please arrange this vehicle to be surveyed soonest possible.

Thank You

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: