

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

DRAFT FINALISATION

M/S : ONG SOCK HOON LENA
58 DA SILVA LANE

SINGAPORE 549785

TEL: 93837726

ATTN:

Claim No: MC1901824

No: MF1901679

Date: 03 Jun 2021

Policy No: MT/00797068

Veh Reg No: SGU8845H

Make/Model: DAIHATSU MATERIA
1.5 A ABS

Your Ref No: CC4/LPC21003543/PA3

Claim Type: Third Party

Accident Date: 14/03/2021

TP Veh Reg No: SGG1889B

Chassis No: JDAM402S001005765

TP Ins Co: LONPAC

DRAFT FINALISATION

Repair Cost to Vehicle No (For Finalization):SGU8845H

Description	Quantity	List Price	Amount
		S\$	S\$
SPARE PARTS			
1 SIDE SKIRT LH	1 PC	350.00	
2 REAR DOOR LH	1 PC	580.00	
3 FRONT DOOR OUTER HANDLE LH	1 PC	68.00	
		998.00	
	Less 15%	149.70	848.30
LABOUR			
4 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	20.00	
5 TO DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM SUCH AS POWER WINDOW MOTOR AND REGULATOR TO NEW DOOR/FACILITATE REPAIR.	1 PC	60.00	
6 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	1 PC	80.00	
7 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	30.00	
8 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD RR FENDER LH.TO KNOCK & REPAIR ROCKER PANEL INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	600.00	
9 TO SPRAY REAR BUMPER,REAR FENDER LH,REAR DOOR LH,FRONT DOOR LH,SIDE SKIRT LH.	1 PC	900.00	
		1,690.00	1,690.00

AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint Singapore 568047
Tel: 6483 1244 Fax: 6483 6170

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

DRAFT FINALISATION

M/S : ONG SOCK HOON LENA
58 DA SILVA LANE

SINGAPORE 549785

TEL: 93837726

ATTN:

Your Ref No: CC4/LPC21003543/PA3

Claim Type: Third Party

Accident Date: 14/03/2021

TP Veh Reg No: SGG1889B

Claim No: MC1901824

No: MF1901679

Date: 03 Jun 2021

Policy No: MT/00797068

Veh Reg No: SGU8845H

Make/Model: DAIHATSU MATERIA
1.5 A ABS

Chassis No: JDAM402S001005765

TP Ins Co: LONPAC

Repair Cost to Vehicle No (For Finalization):SGU8845H

Description	Quantity	List Price	Amount
		S\$	S\$
	Total		S\$ 2,538.30
	Lump Sum Less 20%		-507.66
	Sub Total		S\$ 2,030.64
	Less Rounding		-30.64
	Lum Sum Repair		S\$ 2,000.00
	Add GST @ 7%		140.00
	Total Amount Payable		S\$ 2,140.00

TOTAL: SINGAPORE DOLLAR TWO THOUSAND ONE HUNDRED FORTY ONLY

The above vehicle was surveyed by KENNETH KONG -LKK on 18/03/2021

For AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
Tel: 6483 1244 Fax: 6483 6170
AUTHORISED SIGNATURE

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK-Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

614

SURVEYOR COPY

M/S : ONG SOCK HOON LENA
58 DA SILVA LANE

SINGAPORE 549785

TEL: 93837726

ATTN:

Estimate No: MC1901824

Date: 16 Mar 2021

Policy No: MT/00797068

Veh Reg No: SGU8845H

Make/Model: DAIHATSU MATERIA
1.5 A ABS

Your Ref No: SGU8845H

Claim Type: Third Party

Accident Date: 14/03/2021

TP Veh Reg No: SGG1889B

Not Authorised
C/Ling &
Mechanic After Paint

6 days

Estimate Repair Cost to Vehicle No :SGU8845H

Description	Quantity	List Price S\$	Amount S\$
SPARE PARTS			
1 REAR WINDSCREEN MOULDING TOP - CHECK PRICE	1 PC	na 0.00	X
2 REAR WINDSCREEN MOULDING LH & RH - CHECK PRICE	1 PC	na 0.00	X
3 REAR WINDSCREEN MOULDING BTM - CHECK PRICE	1 PC	na 0.00	X
4 TAILAMP LH - CHECK PRICE	1 PC	na 0.00	X
5 TAILAMP PANEL LH - CHECK PRICE	1 PC	na 0.00	X
6 TAILAMP LOWER BEAM LH - CHECK PRICE	1 PC	na 0.00	X
7 REAR BUMPER - CHECK PRICE	1 PC	na 0.00	X
8 REAR BUMPER SIDE RETAINER LH - CHECK PRICE	1 PC	na 0.00	X
9 REAR BUMPER CLIPS - CHECK PRICE	12 PC	na 0.00	X
10 REAR FENDER LH - CHECK PRICE	1 PC	na 0.00	X
11 REAR FENDER COWLING LH - CHECK PRICE	1 PC	na 0.00	X
12 REAR FENDER COWLING CLIPS - CHECK PRICE	8 PC	na 0.00	X
13 SIDE SKIRT LH - CHECK PRICE	1 PC	na 0.00	350
14 REAR DOOR LH - CHECK PRICE	1 PC	na 0.00	380
15 REAR DOOR RUBBER (AT DOOR) LH - CHECK PRICE	1 PC	na 0.00	X
16 REAR DOOR INNER LOCK LH - CHECK PRICE	1 PC	na 0.00	X
17 FRONT DOOR LH - CHECK PRICE	1 PC	na 0.00	X
18 FRONT DOOR RUBBER (AT DOOR) LH - CHECK PRICE	1 PC	na 0.00	X
19 FRONT DOOR OUTER HANDLE LH - CHECK PRICE	1 PC	na 0.00	68
20 FRONT DOOR OUTER HANDLE COVER LH - CHECK PRICE	1 PC	na 0.00	X
21 FRONT DOOR INNER LOCK LH - CHECK PRICE	1 PC	na 0.00	X
		0.00	0.00
Special Nett			
22 INNER SEAL	1 PC	na 20.00	X
23 WINDSCREEN SEALANT	1 PC	na 40.00	X
24 SPORT RIM LHR - CHECK PRICE	1 PC	na 0.00	X
25 TYRE LHR - CHECK PRICE	1 PC	na 0.00	X
		60.00	60.00



LABOUR

26 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	201
27 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN.	1 PC	na 120.00	X
28 TO DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM SUCH AS POWER WINDOW MOTOR AND REGULATOR TO NEW DOOR/FACILITATE REPAIR.	1 PC	120.00	601

01-04-21
Siang.

06-04-21
man photo.

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : ONG SOCK HOON LENA
58 DA SILVA LANE

SINGAPORE 549785

TEL: 93837726

ATTN:

Estimate No: MC1901824

Date: 16 Mar 2021

Policy No: MT/00797068

Veh Reg No: SGU8845H

Make/Model: DAIHATSU MATERIA
1.5 A ABS

Your Ref No: SGU8845H

Claim Type: Third Party

Accident Date: 14/03/2021

TP Veh Reg No: SGG1889B

Estimate Repair Cost to Vehicle No :SGU8845H

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
29 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	1 PC	180.00	180.00
30 TO REMOVE AND REINSTALL/REPLACE FUEL TANK, FIXTURE AND ATTACHMENTS.	1 PC	60.00	60.00
31 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	60.00	60.00
32 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	60.00	60.00
33 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD RR FENDER LH.TO KNOCK & REPAIR ROCKER PANEL INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	850.00	850.00
34 TO SPRAY REAR BUMPER,REAR FENDER LH,REAR DOOR LH,FRONT DOOR LH,SIDE SKIRT LH.	1 PC	1,000.00	1,000.00
		2,490.00	2,490.00
		Total	S\$ 2,550.00
		Add GST @ 7%	178.50
		Total Amount Payable	S\$ 2,728.50

TOTAL: SINGAPORE DOLLAR TWO THOUSAND SEVEN HUNDRED TWENTY EIGHT AND CENTS FIFTY ONLY

Please arrange this vehicle to be surveyed soonest possible.

Thank You

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE

Resurvey Photos of SGU 8845 H

Daniel @ Ah Lim Motor <Admin2@ahlimmotor.com.sg>

Tue 4/6/2021 2:57 PM

To: Kenneth Kong (LKKAuto) <KennethKong@lkkauto.com>

 9 attachments (609 KB)

DSCN0056(1).JPG; DSCN0057(1).JPG; DSCN0058(1).JPG; DSCN0059(1).JPG; DSCN0060(1).JPG; DSCN0062(1).JPG; DSCN0063(1).JPG; DSCN0064(1).JPG; DSCN0065(1).JPG;

Hi Kenneth,

As attached, the after-paint photos of the vehicle. No check items, no supplementary items.

That is all. Thank you for your attention.

Best Regards,

Daniel Yeo Eng Tah
Ah Lim Motor @ AMK
10, Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint S568047
Tel : 6483 1244 Fax : 6483 6170