

CONNECT 3

566 Woodlands Road (Mandai Estate) Singapore 728697

Tel: (65) 9850-9666 Email: Connect3winnie@gmail.com

R o c : 5 3 3 6 0 0 6 1 L

G S T : 5 3 3 6 0 0 6 1 L

QT21/PA6509R/TPC

China Taiping Insurance (Singapore) Pte Ltd

3 Anson Rd #15-02

Springleaf Tower

Singapore 079909

QUOTATION

Dear Sir,

Cost of Repair to Vehicle PA6509R

With reference to the above-mentioned, we are pleased to quote as follows:-

No.	DESCRIPTION	QTY	U/PRICE (\$\$)	AMOUNT (\$\$)
1.	RH rear view mirror <i>bu✓</i>	1	298.31	298.31
2.	RH rear view mirror (round – bottom) <i>Xsu</i>	1	491.76	491.76
3.	RH rear view mirror (round – side) <i>cm✓</i>	1	415.56	415.56
4.	RH rear view mirror bottom & side bracket (round) <i>& repair</i>	2	105.90	211.80
5.	RH rear view mirror bracket <i>& repair</i>	1	105.90	105.90
6.	Spray painting	1	250.00	250.00
7.	Labour charges	1	300.00	300.00
SUB-TOTAL				SS\$2,073.33

- Price before 7% gst


Thank you.

Yours faithfully,



Winnie Chai

HP: 9850-9666



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*Repair**Ap 90010068**2 days**P/P**25/03/21 @ 1400**Reg after repair**642.48**350.00**992.48**20%**793.98**48-800**2 days**713.87*
10%
*642.48**XR**XR**150**200**350*