

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5922X**AAD2103-079***Not Authorised**83749.90 Pulwary B4 paint*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

16 MAR 2021**SHC5922X**

JTDKB3FU503092624

TOYOTA

PRIUS GEN 4

13/03/2021

AIG

06/11/2020

PART	
1	COVER, REAR BUMPER
1	REINFORCEMENT SUB-ASSY, REAR BUMPER
1	GUARD, REAR BUMPER, CENTER
1	SEAL, REAR BUMPER SIDE, RH
1	RETAINER, REAR BUMPER SIDE, RH
1	LENS & BODY, REAR COMBINATION LAMP, RH
1	LENS & BODY, REAR COMBINATION LAMP, NO.2 RH
1	PANEL SUB-ASSY, QUARTER, RH
1	PANEL SUB-ASSY, REAR DOOR, RH
1	REGULATOR SUB-ASSY, REAR DOOR WINDOW, RH
1	HINGE ASSY, REAR DOOR, LOWER RH
1	HINGE ASSY, REAR DOOR, UPPER RH

LIST	
\$	<i>Bulldo</i> 485.60 ✓
\$	<i>n</i> 332.70 X
\$	<i>sn</i> 374.50 X
\$	<i>sn</i> 118.30 X
\$	<i>sn</i> 132.60 X
\$	<i>sn</i> 339.60 X
\$	<i>cut</i> <i>Gen</i> 261.00 ✓
\$	<i>Re</i> 871.50 ✓
\$	<i>n</i> 1,294.90 X
\$	<i>sn</i> 206.70 X
\$	<i>n</i> 87.10 X
\$	<i>n</i> 98.90 X
TOTAL	\$ 4,603.40
25%	\$ 1,150.85
	\$ 3,452.55

Special Nett

1	REAR BUMPER SIDE CLIP
1	REAR FENDER LINER CLIP
1	TAIL LAMP CLIP
1	TYRE
1	RIM <i>Pr?</i> <i>1555.10 -7256</i>
1	DOOR STICKER TEL NO.
1SET	PARKING AID
1SET	REAR BUMPER CLIP

\$	<i>nn</i> 60.00 ✓ <i>501n</i>
\$	<i>nn</i> 65.00 X
\$	<i>nn</i> 70.00 X
\$	<i>sn</i> 350.00 X
\$	<i>Net</i> 1,879.40 ✓
\$	<i>nn</i> 100.00 X
\$	<i>sn</i> 700.00 X
\$	<i>nn</i> 85.00 X

Trans-cab Auto Services Pte Ltd

AAD2103-079

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5922X

1 REAR BUMPER RETAINER CLIP

	\$	nn	75.00	X
TOTAL	\$		3,384.40	

TOTAL PARTS	\$		6,836.95	
--------------------	----	--	-----------------	--

LABOUR

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$	240.00	301
----	--------	-----

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$	380.00	1001
----	--------	------

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$	1,600.00	6001
----	----------	------

To transfer of rear end panel fittings, attachment to facilitate bodywork repair.

\$	nn	380.00	X
----	----	--------	---

Putty And Spray Painting Of The Affected Portion.

\$	1,600.00	4401
----	----------	------

To reinstall rear bumper parking sensor.

\$	170.00	501
----	--------	-----

To transfer of tire, rim and on wheel balancing.

\$	170.00	201
----	--------	-----

To Check Electrical Lighting Concerned.

\$	170.00	201
----	--------	-----

To check steering geometry and computer wheel alignment

\$	220.00	801
----	--------	-----

To remove and refit of rear fender fittings, attachment and perform water seepage test.

\$	nn	170.00	X
----	----	--------	---

TOTAL	\$		5,100.00	
--------------	----	--	-----------------	--

Over All Total	\$		11,936.95	
-----------------------	----	--	------------------	--

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Trans-cab Auto Services Pte Ltd

AAD2103-079

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5922X

(PART-BY-PART) Repair Days

10-Days

4 days

214038