

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

JHMGK5850FXL03547

ESTIMATE OF REPAIR

Veh# : SGV5648A

TP Ergo
Veron

Model:

HONDA JAZZ

Accident Date : 18/3/2021

(24/7/2015)

Location : PIE TOWARDS TUAS BEFORE JALAN BAHAR EXIT

3P:

GBJ6949Y (ERGO)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Rear bumper <i>Rehnd</i>	640.50	-	-
2	10 pcs	Rear bumper clips <i>New</i>	-	30.00	-
3	2 pcs	Rear bumper o/s & n/s retainer <i>new</i>	86.60	-	-
4	1 pc	Rear tail-gate <i>Dented</i>	1,000.30	-	-
5	1 pc	Rear tail-gate weatherstrip <i>New</i>	239.00	-	-
6	1 pc	Rear tail-gate 'JAZZ' emblem <i>new</i>	66.00	-	-
7	1 pc	Rear tail-gate inner trim <i>AmLd</i>	202.10	-	-
8	8 pcs	Rear tail-gate inner trim clips <i>new</i>	-	24.00	-
9	1 pc	Rear tail gate lock <i>Dmgd</i>	210.00	-	-
10	2pcs	Rear o/s & n/s tail lamp <i>new</i>	880.60	-	-
11	1 pc	Rear end panel <i>Dented</i>	456.50	-	-
12	1 pc	Rear end panel inner trim <i>Dented</i>	110.50	-	-
13	1 pc	Rear windscreen moulding <i>new</i>	286.00	-	-
14	1 pc	Rear windscreen sealant <i>3/100</i>	-	80.00	-
15	1 pc	Rear windscreen inner seal	-	60.00	-
		Sub-Total:	4,178.10	194.00	0.00
		20%		0%	0%
		After Less %:	3,342.48	194.00	0.00
		Labour			
1		To dismantle, straighten and welding.	1,000.00	-	-
2		To spray painting.	800.00	-	-
3		To remove and refit rear windscreen.	160.00	-	-
4		To check wiring.	50.00	-	-
5		To re-seal anti-rust.	50.00	-	-
		Sub-Total:	2,060.00		
		Total:	5,596.48		
		After Less 20%:	4,477.18		

251770 S.N. 134
2014.16

lilan

total: 3748/16

L/S: 3K.

Adrian L

L/S 19/03/21

06 Days

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

• Parts prices are subject to confirmation

• Third party survey is on a "Without Prejudice" basis

• No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SAFE

8778 1999

24 hr accident call

Mobil 1

SGV5648A ESTIMATEPg1

