

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SMM3855H****LAD2103-007***Not Authorized  
Recovery B4 point*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

**15 MAR 2021****SMM3855H**

JTDKB3FUX03083546

TOYOTA

PRIUS

10/03/2021

**AIG**

27/06/2019

<b>PART</b>		<b>LIST</b>	
1	COVER, FRONT BUMPER	\$	516.00 X
1	REINFORCEMENT SUB-ASSY, FRONT BUMPER	\$	716.60 <del>TX</del>
1	ABSORBER, FRONT BUMPER ENERGY	\$	CM 79.60 ✓
1	BRACKET, FRONT BUMPER SIDE, LH	\$	59.30 X
1	BRACKET, FRONT BUMPER SIDE, RH	\$	59.30 X
1	COVER, ENGINE UNDER, NO.1	\$	472.40 X
1	UNIT ASSY, HEADLAMP, LH	\$	2,637.60 X
1	COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	\$	960.50 X
1	UNIT ASSY, HEADLAMP, RH	\$	2,637.60 X
1	COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	\$	960.50 X
1	GRILLE SUB-ASSY, RADIATOR	\$	346.00 ✓
1	GRILLE, RADIATOR, LOWER NO.1	\$	svc 170.10 <del>TX</del>
1	EMBLEM ASSY, RADIATOR GRILLE	\$	90.80 X
<b>TOTAL</b>		<b>\$</b>	<b>9,706.30</b>
<b>25%</b>		<b>\$</b>	<b>2,426.58</b>
		<b>\$</b>	<b>7,279.73</b>

<b>Special Nett</b>			
1SET BUMPER CLIP FRT	\$	95.00	X
1 FRONT NUMBER PLATE WITH MOULDING	\$	200.00	455a
1SET FRNT BUMPER RETAINER CLIP	\$	85.00	X
<b>TOTAL</b>		<b>\$</b>	<b>380.00</b>
<b>TOTAL PARTS</b>		<b>\$</b>	<b>7,659.73</b>

**LABOUR**

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ 380.00 ~~TX~~ X

**Trans-cab Auto Services Pte Ltd****LAD2103-007**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SMM3855H**

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,200.00	1501
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	380.00	X
To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	180.00	X
To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.	\$	480.00	X
To transfer of Fender fittings, attachments and perform water seepage test.	\$	480.00	X
Over All Total \$ 17,640.00			
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	X
To check steering geometry and computer wheel alignment	\$	220.00	X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	250.00	X
Towing Fees	\$	150.00	X
Putty And Spray Painting Of The Affected Portion.	\$	2,200.00	2201
To reinstall rear bumper parking sensor.	\$	170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	X

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SMM3855H**

To transfer of luggage floor panel fittings, attachment and perform water seepage test.

\$ *NA* 380.00 X

To transfer of tire, rim and on wheel balancing.

\$ 4 220.00 X

To replace, refix and top up coolant for radiator

\$ 4 170.00 X

To lift-up / out engine with gear box and refit.

\$ 7 440.00 X

To remove and refit radiator support cross-member and other necessary items to enable bodywork repair.

\$ 4 380.00 X

To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators.

\$ 4 380.00 X

**TOTAL \$ 9,990.00****Over All Total \$ 17,649.73****(PART-BY-PART) Repair Days****25 DAYS***1 1/2 days*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: