

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



Survey & repair
23/03 - 10am ✓

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : **b1 57848**
Date Estimated : **17/03/2021**
Prepared By : **Inthiran A/L Thurasamy**

Page No. : **1 of 5****- ESTIMATE REPAIR FOR -**

Ng Khong Voon
196D West Coast Road

Singapore 127379

- ACCOUNT - 40000

Cash Sales - Service
Singapore

China Taipei

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLV1325Z	WBA2D920605E91563	22/12/2017	216i G TOURER	0

DESCRIPTION

To replace front right door and wing mirror assembly.

To painting front right door and wing mirror cover.

To check electrical wiring system

To transfer lock mechanism from old to new door including
conduct check on new door power window system for proper
function. (1 door).

To carry out body cavity preservation.
(Per panel).

Sundries

VALUE

✓ 1275 1,700.00

✓ 1001 1,113.00

✓ 150 177.00

✓ 451 531.00

✓ 100 118.00

REC

✓ 80.00

Total Labour 1: **3,719.00**DESCRIPTIONQTYPRICVALUE

FRT RH DOOR <i>bt</i>	1	1,142.60	1,142.60
RH MIRROR GLASS HEATED WIDE ANGLE <i>MIS</i>	1	687.20	687.20
RH COVER MIRROR BASE <i>MIS XSVL</i>	1	28.80	28.80
RH OUTSIDE MIRROR COVER CAP PRIMED <i>MIS</i>	1	115.30	115.30
RH SUPPORTING RING <i>MIS</i>	1	58.95	58.95
RH LOWER HOUSING SECTION <i>MIS</i>	1	46.10	46.10
RH WIRING HARNESS EXT. MIRROR HEATE <i>cut XSVL</i>	1	77.10	77.10
Exterior mir <i>MIS</i>	1	496.10	496.10
RH ADDITIONAL TURN INDICATOR LAMP <i>MIS</i>	1	59.65	59.65
FRT RH DOOR BRAKE <i>? XSVL</i>	1	74.60	74.60
FRT DOOR EDGE PROTECTION <i>REC XSVL</i>	1	158.65	158.65
RH SEAL A PILLAR <i>? XSVL</i>	1	48.35	48.35
DRIVE OUTSIDE MEMORY MIRROR <i>MIS</i>	1	441.95	441.95
RH MIRROR ELECTRONICS <i>MIS</i>	1	410.35	410.35

Total Parts : **3,845.70**

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : **b1 57848**
Date Estimated : **17/03/2021**
Prepared By : **Inthiran A/L Thurasamy**

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLV1325Z	WBA2D920605E91563	22/12/2017	216i G TOURER	0

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 23/03/21 @ 1130 Excess S\$ _____

Surveyor's Name RKAM Sign _____

Surveyor's Tel 90010068 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's E-mail _____

No. of Working Days Recommend 4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Labour 1	:	3,719.00
Parts	:	3,845.70
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	529.53
Grand Total	:	8,094.23

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **