

**BCC AUTOMOTIVE PTE LTD**

BLK 1 SIN MING IND. ESTATE SECTOR C
#101/103/105 SINGAPORE 575636
Tel: +65 6552 5588 Fax: +65 6552 7750
Email: enquiry@bcc.sg Website: www.bcc.sg

QUOTATION

Company / GST Reg No : 200507063Z

Quotation No : **SMQ13256**

Quotation : **2021-03-17**
Date

Vehicle Reg No : SFR7140S
Name : AIG ASIA PACIFIC INSURANCE PTE LTD

Make & Model : TOYOTA - CAMRY 2.0
Chassis No : MR053BK3106008745
Mileage : 1 KM
Officer-In-Charge : CHRIS
Page : 1 of 1

No	Description	Unit Price	Qty	Disc (%)	Amount
1	REAR BOOT LID	1413.80	1.00	25.00	1,060.35
2	REAR BOOT LOCK	155.00	1.00	25.00	116.25
3	REAR BOOT CATCH	80.00	1.00	25.00	60.00
4	REAR BOOT GARNISH (CHROME)	155.00	1.00	25.00	116.25
5	REAR BUMPER	794.00	1.00	25.00	595.50
6	REAR BUMPER LH PROTECTOR W/CHROME	95.00	1.00	25.00	71.25
7	REAR BUMPER RETAINER LH	60.00	1.00	25.00	45.00
8	REAR BUMPER RETAINER RH	60.00	1.00	25.00	45.00
9	REAR LH OUTER LAMP	953.60	1.00	25.00	715.20
10	TOYOTA EMBLEM	60.00	1.00	25.00	45.00
11	2.0 EMBLEM	55.00	1.00	25.00	41.25
12	CAMRY EMBLEM	69.00	1.00	25.00	51.75
13	REAR NUMBER PLATE W/FRAME	50.00	1.00		50.00
14	TO PANEL BEAT THE AFFECTED AREA	500.00	1.00		500.00
15	TO SPRAY PAINT ON THE AFFECTED AREA	700.00	1.00		700.00

NOTE:

1. This quotation is only the estimated cost of repair. Any additional works and parts be required during the course of repair, a supplementary quote will be submitted.
2. If you decide to terminate the repair after our diagnosis, a diagnostic fee will apply according to the job performed

Sub-Total : 4,212.80

Add GST 7% : 294.90

Estimated Total Amt (SGD) : 4,507.70

CUSTOMER'S AUTHORISATION

I agree to this quotation and hereby authorize to proceed with the above listed repairs.

CUSTOMER'S SIGNATURE _____

(& Co's Stamp, WHERE NECESSARY)