

**BCC AUTOMOTIVE PTE LTD**

BLK 1 SIN MING IND. ESTATE SECTOR C
#101/103/105 SINGAPORE 575636
Tel: +65 6552 5588 Fax: +65 6552 7750
Email: enquiry@bcc.sg Website: www.bcc.sg

QUOTATION

Company / GST Reg No : 200507063Z

Quotation No : **SMQ13256**

Quotation Date : **2021-03-17**

Vehicle Reg No : SFR7140S
Name : AIG ASIA PACIFIC INSURANCE PTE LTD

Make & Model : TOYOTA - CAMRY 2.0
Chassis No : MR053BK3106008745
Mileage : 1 KM
Officer-In-Charge : CHRIS
Page : 1 of 1

No	Description	Unit Price	Qty	Disc (%)	Amount
1	REAR BOOT LID <i>1143.20</i>	1413.80	1.00	25.00	1,060.35 ✓
2	REAR BOOT LOCK	155.00	1.00	25.00	<i>116.25</i> X
3	REAR BOOT CATCH	80.00	1.00	25.00	<i>60.00</i> X
4	REAR BOOT GARNISH (CHROME)	155.00	1.00	25.00	<i>116.25</i> X
5	REAR BUMPER <i>622.10</i>	794.00	1.00	25.00	<i>595.50</i> ✓
6	REAR BUMPER LH PROTECTOR W/CHROME	95.00	1.00	25.00	<i>71.25</i> ✓
7	REAR BUMPER RETAINER LH	60.00	1.00	25.00	<i>45.00</i> ✓
8	REAR BUMPER RETAINER RH	60.00	1.00	25.00	<i>45.00</i> X
9	REAR LH OUTER LAMP <i>675.20</i>	953.60	1.00	25.00	<i>715.20</i> ✓
10	TOYOTA EMBLEM	60.00	1.00	25.00	<i>45.00</i> ✓
11	2.0 EMBLEM	55.00	1.00	25.00	<i>41.25</i> ✓
12	CAMRY EMBLEM	69.00	1.00	25.00	<i>51.75</i> ✓
13	REAR NUMBER PLATE W/FRAME	50.00	1.00		<i>45.00</i> ✓
14	TO PANEL BEAT THE AFFECTED AREA	500.00	1.00		<i>450.00</i> ✓
15	TO SPRAY PAINT ON THE AFFECTED AREA	700.00	1.00		<i>600.00</i> ✓

*Not Authorised
L/Rmp @ 3200h
Mony After Paint
5 days*

NOTE:

1. This quotation is only the estimated cost of repair. Any additional works and parts be required during the course of repair, a supplementary quote will be submitted to you.
2. If you decide to terminate the repair after our diagnosis, a diagnostic fee will apply according to the job performed.

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sub-Total : 4,212.80
Add GST 7% : 294.90
Estimated Total Amt (SGD) : **4,507.70**

CUSTOMER'S AUTHORIZATION

I agree to this quotation and hereby authorize to proceed with the above listed repairs.

CUSTOMER'S SIGNATURE _____

(& Co's Stamp, WHERE NECESSARY)

**BCC AUTOMOTIVE PTE LTD**

BLK 1 SIN MING IND. ESTATE SECTOR C
#101/103/105 SINGAPORE 575636
Tel: +65 6552 5588 Fax: +65 6552 7750
Email: enquiry@bcc.sg Website: www.bcc.sg

QUOTATION

Company / GST Reg No : 200507063Z

Quotation No : **SMQ13294**

Quotation : **2021-03-17**
Date

Vehicle Reg No : SFR7140S
Name : AIG ASIA PACIFIC INSURANCE PTE LTD

Make & Model : TOYOTA - CAMRY 2.0
Chassis No : MR053BK3106008745
Mileage : 1 KM
Officer-In-Charge : CHRIS
Page : 1 of 1

No	Description	Unit Price	Qty	Disc (%)	Amount
1	REAR END PANEL <i>675.00</i>	834.30	1.00 <i>13</i>	25.00	625.73 ✓
2	REVERSE SENSOR	280.00	1.00	<i>7%</i>	280.00 <i>200%</i>
3	TO SPRAY THE REAR END PANEL & THE REAR LH FENDER	300.00	1.00		300.00 <i>18%</i>

NOTE:

1. This quotation is only the estimated cost of repair. Any additional works and parts be required during the course of repair, a supplementary quote will be submitted.
2. If you decide to terminate the repair after our diagnosis, a diagnostic fee will apply according to the job performed

Sub-Total : 1,205.73
Add GST 7% : 84.40
Estimated Total Amt (SGD) : **1,290.13**

CUSTOMER'S AUTHORISATION

I agree to this quotation and hereby authorize to proceed with the above listed repairs.

CUSTOMER'S SIGNATURE _____

(& Co's Stamp, WHERE NECESSARY)