

Premium Carz

Services Pte Ltd

Co. Reg. No.: 201416720C
1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883
Tel : 6636 9100 Fax : 6636 9113

Date : 18/03/2021

TO: AIG ASIA PACIFIC INSURANCE PTE LTD
AIG Building
78 Shenton Way, #07-16
Singapore 079120

Our Customer : Yue Loy Trading
Vehicle No : GBE5527P
Model : Toyota Dyna 3.0 M
Manufacture Year : 2015
Date of Accident : 15/03/2021
Total Estimate Repair Days : 7
Total Pages : 2

Attn : Motor Claims Department
Fax : 6415 3727

Re: Repair Estimate For Third Party Claim against SLT1438S

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	Spare Parts				
1	Front bumper <i>Best Quality</i>	1	\$498.50	\$498.50	✓
2	Front bumper reinforcement <i>new</i>	1	\$165.00	\$165.00	x
3	Front corner panel RH <i>new</i>	1	\$279.30	\$279.30	x
4	Front grille <i>new</i>	1	\$501.50	\$501.50	x
5	Front grille clip <i>new</i>	10	\$5.00	\$50.00	20
6	Front grille rubber seal <i>new</i>	1	\$128.00	\$128.00	x
7	Front grille "Toyota" logo <i>new</i>	1	\$61.50	\$61.50	✓
8	Headlamp RH <i>new</i>	1	\$1,140.00	\$1,140.00	126.
9	Headlamp lower seal RH <i>new</i>	1	\$75.00	\$75.00	x
10	Front door RH <i>Dented</i>	1	\$1,550.00	\$1,550.00	1349.
11	Front door lower rubber RH <i>new</i>	1	\$85.50	\$85.50	x
12	Front door weatherstrip RH <i>new</i>	1	\$195.60	\$195.60	x
13	Front door weatherstrip RH <i>new</i>	1	\$201.75	\$201.75	x
14	Front door chanel RH <i>new</i>	1	\$109.30	\$109.30	x
15	Front door outer moulding RH <i>new</i>	1	\$109.30	\$109.30	x
16	Front door hinges RH <i>Best Lower</i>	2	\$89.50	\$179.00	89.50
17	Front door check RH <i>new</i>	1	\$196.30	\$196.30	x
18	Front door step panel RH <i>new</i>	1	\$300.00	\$300.00	x
	Total			\$5,716.25	
			Less 25%	\$1,429.06	
	Sub Total 1			\$4,287.19	
A.	Spare Parts (S/Nett)				
1	Company registration sticker (set) <i>new</i>	1	\$80.00	\$80.00	30
2	Company sticker <i>new</i>	1	\$100.00	\$100.00	60
3	Fog lamp RH <i>new</i>	1	\$0.00	\$0.00	x
4	Front door signal lamp RH <i>new</i>	1	\$148.00	\$148.00	✓
	Sub-Total 2			\$328.00	
	Total for Parts			\$4,615.19	
B.	Labour				
1	To check wiring.			\$60.00	30
2	Panel beating charges to remove and replace, to cut and weld, to knock and reshape damaged parts & areas.			\$800.00	500
3	Spray painting all affected parts & areas.			\$800.00	600
4	To spray anti-rust undercoat.			\$60.00	30
5	To remove and refit front door glass RH.			\$100.00	80

1240

Co. Reg. No.: 201416720C

1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883

Tel : 6636 9100 Fax : 6636 9113

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
				Total Labour	\$1,820.00
				Total Repair Cost	\$6,435.19

Yours faithfully,

Aun Teng

f Premium Carz Services Pte Ltd

Surveyor's Details	
Name	Adnan
Contact	96893735
Survey Date	19/03/21
Recommender	Authorize / Not Authorize
Before Paint	Yes / No

kump sum

05 Days.

Total: 3912.50

L/S: 3.1K ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: