



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643
TEL: 6453 1235, 6452 0850 FAX: 6453 7944
24hrs Towing Services Tel 9823 9898
Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

Estimate : QUOT202103-000639(00)

CHINA TAIPING INSURANCE (S) PTE LTD
NO. 3
ANSON RD
SPRINGLEAF TOWER
SINGAPORE 079909

Contact : -

Fax No. : 62247175

NOT Authorized
11 Day @ 10,750/-
Recovery After Paint
10 days

Date : 18/03/2021
Vehicle No. : SLF6445L
Make/Model : TOYOTA VELLFIRE 2.5Z G-EDITION
A
Mileage (km) : 0
Chassis No. : AGH300038172 (01/09/2016)
Accident Date : 17/03/2021 00:00:00
Claim No. : SGS5310P
Reference : JO202103-0812
Policy No. : G300336831MCY

S/No	Particular	Quantity	Unit Price	Amount S\$
------	------------	----------	------------	------------

LIST ITEMS :

1	Bonnet	1.0	855.60	855.60 ✓
2	Bonnet hinge	2.0	58.90	117.80 X
3	Bonnet lock	1.0	135.00	135.00 X
4	Bonnet chrome moulding	1.0	553.60	553.60 ✓
5	LH headlamp <i>4100.10</i>	1.0	<i>CM</i> 4,424.80	4,424.80 ✓
6	LH headlamp garnish	1.0	104.60	104.60 ✓
7	LH headlamp ECU	1.0	967.40	967.40 X
8	Front bumper	1.0	632.30	632.30 ✓
9	Front bumper sponge	1.0	79.60	79.60 X
10	Front bumper reinforcement <i>352.80</i>	1.0	466.40	466.40 ✓
11	Front bumper retainer	2.0	68.20	136.40 ✓
12	Front bumper LH grille	1.0	241.90	241.90 ✓
13	Front bumper LH grille cover	1.0	54.70	54.70 ✓
14	Front bumper garnish	1.0	219.00	219.00 X
15	Front bumper lower grille	1.0	206.30	206.30 X
16	Front bumper support bracket	2.0	100.40	200.80 X
17	Front bumper lower absorber	1.0	155.70	155.70 X
18	LH Fog Lamp	1.0	516.00	516.00 ✓
19	Front LH parking sensor with cap	1.0	392.80	392.80 X
20	Front grille <i>1241.90</i>	1.0	<i>nd/l</i> 1,537.50	1,537.50 ✓
21	Rear bumper <i>1217</i>	1.0	1,853.00	1,853.00 ✓
22	Rear bumper side support	2.0	98.00	196.00 X
23	Rear bumper retainer	2.0	103.40	206.80 ✓
24	Rear bumper tow cover LH	1.0	19.60	19.60 ✓
25	Rear bumper reflector LH	1.0	90.80	90.80 ✓
26	Rear Bumper clips	8.0	4.21	33.68 ✓
27	Rear parking sensor with cap <i>265</i>	3	392.80	1,178.40 ✓
28	Rear LH under cover	1.0	252.10	252.10 X
29	Tailgate <i>1718</i>	1.0	2,040.50	2,040.50 ✓
30	Tailgate lock	1.0	800.20	800.20 X
31	Tailgate striker	1.0	41.00	41.00 X
32	Tailgate weatherstrip <i>335.20</i>	1.0	372.30	372.30 ✓
33	Tailgate emblem - Vellfire	1.0	61.70	61.70 ✓
34	Rear end panel <i>745.20</i>	1.0	781.70	781.70 ✓



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE #01-60/62, SIN MING ROAD, SINGAPORE 575643

TEL: 6453 1235, 6452 0850 FAX: 6453 7944

24hrs Towing Services Tel 9823 9898

Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

Estimate : QUOT202103-000639(00)

Date : 18/03/2021

Vehicle No. : SLF6445L

Make/Model : TOYOTA VELLFIRE 2.5Z G-EDITION A

Mileage (km) : 0

Chassis No. : AGH300038172

Accident Date : 17/03/2021 00:00:00

Claim No. : SGS5310P

Reference : JO202103-0812

Policy No. : G300336831MCY

CHINA TAIPING INSURANCE (S) PTE LTD

NO. 3

ANSON RD

SPRINGLEAF TOWER

SINGAPORE 079909

Contact : -

Fax No. : 62247175

S/No	Particular	Quantity	Unit Price	Amount S\$
35	Rear end panel top garnish	1.0	167.30	167.30 ✓
36	Rear end panel trims	2.0	481.90	963.80 ✗
37	Rear keyless entry antenna	1.0	189.70	189.70 ✗
38	Spare wheel protector	1.0	376.20	376.20 ✗
39	Spare wheel carrier	1.0	37.60	37.60 ✗
List Total :				22,053.38
25% Discount S\$				5,513.28
				16,540.10

LABOUR :

* To remove and refit rear windscreen glass	1.0	100.00	100.00 ✓
- To recalibrate/ reset tailgate power door system	1.0	150.00	150.00 100%
- To check wiring and lighting	1.0	60.00	60.00 40%
- To remove and refit rear trims, upholstery and seats	1.0	220.00	220.00 120%
- To supply panel sealant and to seal off all weld spot seams and gaps	1.0	90.00	90.00 305%
- To spray ribberized under coating	1.0	120.00	120.00 90%
-To knock jackout damaged parts, panel beating,welding, align, refix and to renew accident parts	1.0	1,400.00	1,400.00 1000%
- Spray painting on affected & replace parts	1.0	1,600.00	1,600.00 1400%
			3,740.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

E & O E

Acknowledged by Repairer

Signature:

Date:

Total S\$: 20,280.10

GST 7% S\$: 1,419.61

Amount Due S\$: 21,699.71