

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKZ 49T

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	O/S FRONT FENDER EMBLEM (N)	DAMAGED	67.00	67.00
1	O/S FRONT FENDER CHROME MOULDING (N)	DAMAGED	139.00	139.00
1	O/S FRONT WHEEL RIM (N)	DENTED / WARPED	1,450.00	1,450.00
1	O/S FRONT WHEEL BEARING (N)	DAMAGED	726.00	726.00
1	O/S FRONT SHOCK ABSORBER (N)	NOT NECESSARY	3,445.00	-
1	O/S FRONT KNUCKLE ARM (N)	NOT NECESSARY	1,215.00	-
1	O/S FRONT UPPER ARM (N)	NOT NECESSARY	895.00	-
1	O/S FRONT LOWER ARM (N)	NOT NECESSARY	872.00	-
1	O/S FRONT STRUT ARM (N)	NOT NECESSARY	695.00	-
	LESS 10% DISCOUNT		-950.40	-238.20
			8,553.60	2,143.80
	<u>LABOUR</u>			
	LABOUR CHARGES TO REPAIR, PANEL BEAT AND STRAIGHTEN DAMAGED PARTS.		700.00	250.00
	TO DISMANTLE / REPLACE O/S FRONT SUSPENSION & UNDERCARRIAGE PARTS.		350.00	80.00
	TO REPLACE O/S FRONT WHEEL RIM INCLUDE WHEEL BALANCING.		120.00	60.00
	TO CHECK & ADJUST WHEEL ALIGNMENT & STEERING GEOMETRY. (BEFORE & AFTER).		240.00	100.00
	TO RESET ELECTRICAL MODULE SYSTEM.		280.00	120.00
	TO PUTTY, APPLY PRIMER & SPRAY-PAINT THE AFFECTED AREAS.		850.00	500.00
			2,540.00	1,110.00
	GRAND TOTAL		11,093.60	3,253.80
	PECOMMENDED COST OF LUMP SUM PEDAIDS			2 600 00

RECOMMENDED COST OF LUMP SUM REPAIRS		2,600.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS1/LAW21003564/Avd3e2



ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.