



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2103383

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 14/05/2021
Reference CC3/CTI21003565/Ges3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SHD 1076J
Insured Veh. SKC 3086L
Claim No. SNM21D201552
Policy No. DMPCSNW00176022008
Accident Date 18/03/2021
Inspection Date 19/03/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Ref: CC3/CTI21003565/Ges3q2	
			Date: 14/05/2021	
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKC 3086L	Veh. Inspected	SHD 1076J	
Policy No.	DMPCSNW00176022008	Coverage (\$)	0.00	
Claim No.	SNM21D201552	Excess (\$)	0.00	
Assign From		Assign Date	19/03/2021	
2. Vehicle Particulars & Condition				
Make & Model	KIA OPTIMA 1.7	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	KNAGM414MF5659205	Colour	SILVER	
Odometer	686316 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/65 R16	HANKOOK	6 mm	
L/H Front Tyre	205/65 R16	HANKOOK	6 mm	
R/H Rear Tyre	205/65 R16	HANKOOK	6 mm	
L/H Rear Tyre	205/65 R16	HANKOOK	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	18/03/2021	Inspection Date	19/03/2021	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 1076J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT O/S HEADLAMP	NOT NECESSARY	1,028.00	-
1	FRONT BUMPER	TO REPAIR SEE LABOUR	531.00	-
1	FRONT BUMPER EMBLEM	NECESSARY	44.00	44.00
1	FRONT BUMPER O/S PROTECTOR	NOT NECESSARY	51.00	-
1	FRONT BUMPER O/S FOG LIGHT COBER	NOT NECESSARY	66.00	-
1	FRONT O/S FENDER	BUCKLED	384.00	384.00
1	FRONT O/S FENDER INNER SHIELD	NOT NECESSARY	120.00	-
2	FRONT BUMPER O/S SIDE RETAINER @\$16.00	NOT NECESSARY	32.00	-
1	O/S MIRROR ASSY	NOT NECESSARY	590.00	-
1	FRONT O/S DOOR	TO REPAIR SEE LABOUR	791.00	-
1	FRONT O/S WHEEL COVER	SCRATCHED	116.00	116.00
1	O/S ROCKER PANEL GARNISH	TO REPAIR SEE LABOUR	286.00	-
1	FRONT O/S RIM	NOT NECESSARY	246.00	-
	LESS 10% DISCOUNT		-428.50	-54.40
			3,856.50	489.60
<u>SPECIAL NETT ITEMS</u>				
1	FRONT BUMPER CLIPS (SN)	NECESSARY	48.00	48.00
1	FRONT O/S FENDER STICKER (SN)	NECESSARY	30.00	30.00
1	SET FRONT O/S FENDER INNER SHIELD CLIPS (SN)	NECESSARY	28.00	28.00
1	SET O/S DOOR STICKERS (SN)	NECESSARY	100.00	100.00
1	SUNDRY (SN)	NOT NECESSARY	50.00	-
			256.00	206.00
<u>LABOUR</u>				
	TO CHECK FRONT N/S & O/S WHEEL ALIGNMENT .		80.00	60.00
	TO REFIT /DISMANTLE INNER COMPONENTS OF THE FRONT O/S DOOR ONTO NEW SHELL DOOR .	NOT NECESSARY	150.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING KNOCK-OUT ,STRAIGHTEN ,REPAIR ,RESHAPE AND ADJUST OF THE SAME,ETC.INCLUSIVE OF THE REPAIR OF FRONT BUMPER ,FRONT O/S DOOR AND O/S ROCKER PANEL GARNISH .		1,000.00	400.00
	TO PUTTY AND SPRAY PAINTING ON FRONT BUMPER ,FRONT O/S FENDER,O/S MIRROR COVER ,FRONT O/S DOOR ,O/S ROCKER PANEL GARNISH .		1,000.00	800.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.		120.00	60.00
			2,350.00	1,320.00
GRAND TOTAL			6,462.50	2,015.60
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,600.00

Report Ref No. CC3/CTI21003565/Ges3q2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 1076J

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 1076J

RE-INSPECTION

