

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

5 Days.
Lump sum repair
After repair photos.
4/3/21
Guo Qir

18-Mar-21

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1076 J

1 pc	Front o/s headlamp	X NN	\$	1,028.00
1 pc	Front bumper	X Repair	\$	531.00
1 pc	Front bumper emblem	/ mcl	\$	44.00
1 pc	Front bumper o/s protector	X NN	\$	51.00
1 pc	Front bumper o/s fog light cover	X NN	\$	66.00
1 pc	Front o/s fender	/ mcl	\$	384.00
1 pc	Front o/s fender inner shield	X NN	\$	120.00
2 pcs	Front bumper o/s side retainer	@ \$16.00 X NN	\$	32.00
1 pc	o/s mirror assy	X NN	\$	590.00
1 pc	Front o/s door	X Repair	\$	791.00
1 pc	Front o/s wheel cover	/ mcl	\$	116.00
1 pc	o/s rocker panel garnish	X Repair	\$	286.00
1 pc	Front o/s rim	X NN	\$	246.00

LKK Auto Consultants hence notify the Reparer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplier's item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Reparer
Signature:
Date:

S/NETT

1 pc	Front bumper clips	/ mcl	\$	48.00
1 pc	Front o/s fender sticker	/ mcl	\$	30.00
1 set	Front o/s fender inner shield clips	/ mcl	\$	28.00
1 set	o/s door stickers	/ mcl	\$	100.00

Sundry \$ 50.00 X NN

To check front n/s & o/s wheel alignment \$ 80.00 60

To refit/dismantle inner components of the front o/s door onto new shell door \$ 150.00 X NN

To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc. \$ 1,000.00 400

To putty and spray painting on front bumper, front o/s fender, o/s mirror cover, front o/s door, o/s rocker panel garnish \$ 1,000.00 800

To apply rustproofing on the repaired and replaced panels. \$ 120.00 60.
\$ 6,462.50

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)