

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

18-Mar-21

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1076 J

1 pc	Front o/s headlamp	X NN	\$ 1,028.00
1 pc	Front bumper	X Repair	\$ 531.00
1 pc	Front bumper emblem	/ mcl	\$ 44.00
1 pc	Front bumper o/s protector	X } NN	\$ 51.00
1 pc	Front bumper o/s fog light cover	X } NN	\$ 66.00
1 pc	Front o/s fender	/ mcl	\$ 384.00
1 pc	Front o/s fender inner shield	X	\$ 120.00
2 pcs	Front bumper o/s side retainer	@ \$16.00 X T NN	\$ 32.00
1 pc	o/s mirror assy	X NN	\$ 590.00
1 pc	Front o/s door	X Repair	\$ 791.00
1 pc	Front o/s wheel cover	/ scf	\$ 116.00
1 pc	o/s rocker panel garnish	X Repair	\$ 286.00
1 pc	Front o/s rim	X NN	\$ 246.00

Date: _____
 Signature: _____
 Acknowledged by Repairer: _____
 LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplier's name(s) must be resurveyed and
 is subject to final approval from Insurance Company

S/NETT

1 pc	Front bumper clips	/ mcl	\$ 48.00
1 pc	Front o/s fender sticker	/ mcl	\$ 30.00
1 set	Front o/s fender inner shield clips	/ mcl	\$ 28.00
1 set	o/s door stickers	/ mcl	\$ 100.00

Sundry	\$ 50.00	X NN
To check front n/s & o/s wheel alignment	\$ 80.00	60
To refit/dismantle inner components of the front o/s door onto new shell door	\$ 150.00	X NN
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc.	\$ 1,000.00	400
To putty and spray painting on front bumper, front o/s fender, o/s mirror cover, front o/s door, o/s rocker panel garnish	\$ 1,000.00	800
To apply rustproofing on the repaired and replaced panels.	\$ 120.00	60
	<u>\$ 6,462.50</u>	

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

5 Days.
 Lump sum repair
 After repair photos.
 4/3/21
 Gao Qr-P