



凱摩哆服務

KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701.
TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com
BUS. REG. NO: 44223100L GST NO: M90371531Y

專業服務：汽車意外保險賠償，拖車，汽車修理及維修服務，打嗎呷，噴漆。

Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting.

Date : 17/03/2021

Attn: The Motor Claims Department

Your Insured veh no : GBK 85 Z

VSKYBAM2020090105

MSIG Insurance (S) Pte Ltd

4 Shenton Way

#21-01 SGX Centre 2

Singapore 068807

Tel : 6827 7888

Fax : 6827 7809

Veron

WITHOUT PREJUDICE

LKK Auto Consultants hence notify
(By Email Only) of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Dear Sir / Madam

Estimate Cost of Repair for Nissan NV200 GBD 4380 G & GBK 85 Z ON 11/03/2021 AT 17:00.

Acknowledged by Repairer
Signature:
Date:

To Supply :-

1pc	Rear Boot Cover LH	Dented	\$	1,469.60	Nett ✓
1pc	Rear Boot Cover "Nissan" Logo		\$	79.00	Nett ✓
1pc	Rear Boot Cover "NV 200" Plate	3424.80	\$	145.00	Nett ✓
1pc	70km/h Sticker	3082.32	\$	24.00	Nett 10/500.
1pc	Rear Lamp LH	Not Nee	\$	277.40	Nett x
1pc	Rear Boot Cover RH	Dented	\$	1,002.50	Nett ✓
1pc	Rear Boot Cover Dci Plate	Not Nee	\$	96.00	Nett ✓
2pcs	Rear Boot Cover Number Plate Lamp Garnish	Not Nee	\$	352.00	Nett x
1pc	Rear Bumper	Deformed	\$	632.70	Nett ✓
1pc	Rear Boot Cover Inner Lock	Not Nee	\$	330.00	Nett x
			\$	4,408.20	
		Less 10%	-\$	440.82	
			\$	3,967.38	
1set	Body Lettering Logo	Nee	\$	750.00	S/nett 550
1pc	Rear boot cover windscreen glass seal	Nee	\$	65.00	S/nett ✓
1set	Reverse Sensor	Damaged	\$	350.00	S/nett 200
			\$	1,165.00	

To dismantl & replace damage parts, panel beat where necessary

To putty, apply primer & spray paint on the affected portion.

labour charge to remove & refix Rear windscreen

To remove uphdstery.

To check wiring functions.

To remove reverse sensor.

1460 \$ 780.00 600
\$ 800.00 600
\$ 160.00 120
\$ 80.00 60
\$ 80.00 30
\$ 80.00 30
05 Apr \$ 7,112.38

Total: 5357.32

L/S: A250