

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: EQ Insurance Company Ltd
5 Maxwell Road, #17-00 Tower Block
MND Complex
Singapore 069110

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Joel Goh

Date: 23 Mar 2021

Preliminary Advice

Vehicle No	: SMM1383R	Accident Date	: 13/03/2021
Make	: BMW M3	Policy No.	: DMPPHQ20-008729
Assignment Date	: 17/03/2021	Excess	: S\$4,000.00
Date of Inspection	: 18/03/2021	Est. Duration of Repair	: 5
Inspection At	: TEAMWORK GARAGE PTE LTD (HQ) 53 UBI AVE 1 #01-24, PAYA UBI INDUSTRIAL PARK SINGAPORE 408934		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	34,700.70
Revised Amount	:S\$	12,228.51
Check Items (Estimated)	:S\$	12,952.20
Total	:S\$	25,180.71

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	127,400.00
COE / PARF Rebate	:S\$	79,265.00
Salvage Value	:S\$	
Margin for Repair	:S\$	48,135.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Repairer is asking for part by part as there is no 2nd hand part. Parts price to be confirm upon finalization