

OWN DAMAGE CLAIM

EQ

Vehicle number	SMM1383R
Make / Model	BMW M3
Chassis number	WBSKG920X0E698568
Accident date	13/3/21
Reference	2103-26

Qty	Particulars	Unit Price - SGD \$
	<u>PARTS REPLACEMENT - LIST ITEMS</u>	
1	AIR INTAKE HOSE ?	178.00
1	AIR INTAKE BOX ?	1044.00
1	TURBO CHARGE PIPE ?	180.00
1	RESERVIOR COOLANT TANK ?	204.00
1	INLET PIPE ?	252.00
1	OUTLET PIPE ?	150.00
1	ALTERNATOR ?	768.00
1	INTAKE MANIFOLD ?	1920.00
1	OIL COOLER ?	516.00
2	FRONT HEADLAMP / <i>CRD</i>	3120.00
2	FRONT HEADLAMP BRACKET ?	204.00
2	HEADLAMP BALLAST X	720.00
2	HEADLAMP CONTROL MODULE X <i>WV</i>	564.00
1	FRONT BUMPER - <i>de</i>	1440.00
2	FRONT BUMPER RETAINER - <i>de</i>	28.00
1	FRONT BUMPER TOW COVER - <i>mis.</i>	48.00
1	FRONT BUMPER LOWER GRILLE ?	105.00
1	FRONT BUMPER SPONGE ?	51.00
1	FRONT BUMPER REINFORCMENT ?	1140.00
2	FRONT NOZZLE - <i>mis</i>	336.00
2	FRONT NOZZLE COVER - <i>mis.</i>	108.00
4	FRONT PDC SENSOR ?	408.00
1	FRONT NUMBER PLATE BASE - <i>Ant.</i>	108.00
2	FRONT GRILLE LH/RH - <i>Dis.</i>	288.00
1	AIRDUCT FRONT ?	96.00
1	AIRDUCT CENTRE ?	96.00
1	RADIATOR ?	840.00
1	RADIATOR FAN HOUSING ?	396.00
1	RADIATOR HOSE ?	52.00
1	RADIATOR UPPER HOSE ?	96.00
1	RADIATOR LOWER HOSE ?	110.00
1	EXPANSION TANK ?	192.00
1	EXPANSION TANK CAP ?	27.00
1	COMPRESSOR X <i>NN</i>	2760.00
1	AIRCON CONDENSER	264.00
1	AIRCON SUCTION PIPE ?	324.00
1	AIRCON LIQUID PIPE ?	216.00
1	AIRCON DISCHARGE PIPE ?	312.00
1	FRONT TOP PANEL / <i>BT.</i>	684.00

1	FRONT TOP PANEL SEAL / <i>W1</i>	32.00
1	AIR GUIDANCE ?	96.00
1	BONNET / <i>fine</i>	2976.00
2	BONNET HINGE X <i>NN</i>	124.00
2	BONNET LOCK <i>?</i>	172.00
2	BONNET LOCK CATCH <i>?</i>	64.00
2	BONNET LOCK CATCH BRACE BRACKET - <i>BT</i>	43.00
1	BONNET WEATHERSTRIP X <i>NN</i>	38.00
1	BONNET EMBLEM / <i>MSC</i>	78.00
2	BONNET CABLE X <i>NN</i>	40.00
1	FAN BELT ?	30.00
1	FAN BELT TENSIONAL ?	294.00
1	GEAR BOX COOLER ?	528.00
1	WIPER WASHER TANK ?	177.00
		25037.00
Cost +10%		2503.70
Subtotal		27540.70
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
1 SET	FRONT BUMPER CLIP / <i>MSC</i>	30.00
1 SET	BONNET INSULATOR CLIP X <i>NN</i>	40.00
1	FRONT NUMBER PLATE / <i>CRA</i>	80.00
1	JOINT SEALANT X <i>NN</i>	150.00
1 BOT	COOLANT / <i>MSC</i>	150.00
Subtotal		450.00
Balance C/F		27990.70
<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
1	CHECK WIRING AND LIGHTNING SYSTEM	60.00 <i>30</i>
2	REMOVE AND REFIT RADIATOR AND TOP UP COOLANT	200.00 <i>100</i>
3	REMOVE AND REFIT CONDENSER AND TOP UP GAS	200.00 <i>100</i>
4	MOUNT VEHICLE ON BENCH FOR CHASSIS REPAIR	500.00 X <i>NN</i>
5	RE-PROGRAMME OF HEADLAMP MODULE AFTER REPAIR	300.00 <i>?</i>
6	DIAGNOSIS CHECK AFTER REPAIR	300.00 X
7	REMOVE AND REPLACE PDC SENSOR	200.00 <i>40</i>
8	PANEL BEATING ON AFFECTED AREAS	2400.00 <i>700</i>
9	SPRAY PAINTING ON AFFECTED AREAS	2400.00 <i>800</i>
10	APPLY ANTI RUST ON AFFECTED AREAS	150.00 X <i>NN</i>
Subtotal		6710.00
Grand total		34700.70

5 Days.
 part by part.
 before paint photos
 Gue Qiang
 82880282
 18/3/21

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: