

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB7784U

AAD2012-142

Not Authored

Account B4 paint

8740h

Vehicle No.:		SHB7784U
Chassis No.:		JTDKB3FU003077318
Vehicle Make:	15 MAR 2021	TOYOTA
Vehicle Model:		PRIUS
Date of Accident :		17/12/2020
Third Party Insurer :		CHINA
Date of Registration:		12/12/2018

PART	LIST		
1 COVER, REAR BUMPER		\$	<i>n</i> 442.60 X
1 COVER, REAR BUMPER, LOWER		\$	<i>sn</i> 15.40 X
1 RETAINER, REAR BUMPER SIDE, RH		\$	<i>sn</i> 117.70 X
1 SEAL, REAR BUMPER SIDE, RH		\$	<i>sn</i> 88.50 X
1 PANEL SUB-ASSY, QUARTER, RH		\$	<i>n</i> 871.50 X
	TOTAL	\$	1,535.70
	25%	\$	383.93
		\$	1,151.78

Special Nett			
1SET PARKING AID		\$	<i>sn</i> 700.00 X
1SET REAR BUMPER CLIP		\$	<i>nn</i> 95.00 X
1 REAR BUMPER PROTECTOR		\$	<i>nn</i> 180.00 X
1SET REAR BUMPER RETAINER CLIP		\$	<i>nn</i> 85.00 X
1 TYRE		\$	<i>sn</i> 350.00 X
1 RIM		\$	<i>sn</i> 1,879.40 X
	TOTAL	\$	3,289.40

TOTAL PARTS \$ 4,441.18

LABOUR

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair. \$ 380.00 X

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same \$ 2,200.00 *300l*

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB7784U**AAD2012-142**

To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	na	380.00	X
To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	na	180.00	X
To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.	\$	na	480.00	X
			<u>TOTAL \$</u>	<u>9,900.00</u>
To transfer of Fender fittings, attachments and perform water seepage test.	\$	na	480.00	X
			<u>Over All Total \$</u>	<u>na</u>
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	na	380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	na	380.00	X
To check steering geometry and computer wheel alignment	\$	na	220.00	X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	na	250.00	X
Towing Fees	\$	na	150.00	X
Putty And Spray Painting Of The Affected Portion.	\$		2,200.00	4801
To reinstall rear bumper parking sensor.	\$	na	170.00	X
To Check Electrical Lighting Concerned.	\$	h	170.00	X
To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	h	380.00	X
To transfer of tire, rim and on wheel balancing.	\$	h	220.00	X
To replace, refix and top up coolant for radiator	\$	h	170.00	X

Trans-cab Auto Services Pte Ltd

AAD2012-142

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB7784U

To lift-up / out engine with gear box and refit. \$ *un* 440.00 X

To remove and refit radiator support cross-member and other necessary items to enable bodywork repair. \$ 380.00 X

To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators. \$ 380.00 X

TOTAL \$ 9,990.00

Over All Total \$ 14,431.18

(PART-BY-PART) Repair Days ~~25~~ DAYS

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: