

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

JENNIFER LEE LIPING

61 MOUNT SINAI DRIVE #14-03

SINGAPORE 277113

Contact : 82339929

TP Budget Direct
Veron**ESTIMATE**

Repair Code : CLM15207

Date in : 18/03/2021

Vehicle Num. : SMP3350G

Model : TOYOTA HARRIER M GARDE

Chassis/Eng# : JTEZB3GH90J004908/8ARZ165423

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Rehd</i>	1	1217.40	<i>782</i> 1,217.40
REAR BUMPER INNER SPONGE <i>could</i>	1	172.25	<i>✓</i> 172.25
REAR BUMPER LID GARNISH <i>Rehd</i>	1	481.00	<i>✓</i> 481.00
REAR BUMPER REFLECTOR L/R <i>could</i>	2	114.20	<i>✓</i> 228.40
REAR BUMPER REINFORCEMENT (GAS) <i>Bent</i>	1	1045.30	<i>✓</i> 1,045.30
REAR BUMPER REVERSE SENSOR <i>2 piece dry d</i>	4	235.00	<i>470</i> 940.00
REAR BUMPER REVERSE SENSOR BRACKET <i>seen</i>	4	55.00	<i>+</i> 220.00
REAR BUMPER REVERSE SENSOR COVER <i>seen</i>	4	59.00	<i>+</i> 236.00
REAR BUMPER SIDE RETAINER L/R <i>Ret could</i>	2	122.50	<i>122.50</i> 245.00
REAR END PANEL <i>Dented</i>	1	781.85	<i>✓</i> 781.85
REAR END PANEL ANTENNA SENSOR <i>could</i>	1	255.00	<i>✓</i> 255.00
REAR END PANEL INNER TOP GARNISH <i>seen</i>	1	591.60	<i>+</i> 591.60
REAR RH TAILLAMP <i>seen</i>	1	581.90	<i>+</i> 581.90
REAR TAILGATE <i>Dented</i>	1	2379.00	<i>1850</i> 2,379.00
REAR TAILGATE 'HARRIER' EMBLEM <i>seen</i>	1	121.25	<i>✓</i> 121.25
REAR TAILGATE 'TURBO' EMBLEM <i>seen</i>	1	121.25	<i>✓</i> 121.25
REAR TAILGATE INNER PULL GARNISH <i>seen</i>	1	174.35	<i>+</i> 174.35
REAR TAILGATE INNER RUBBER GUIDE STOPPER L/R <i>seen</i>	2	43.75	<i>+</i> 87.50

*** This is a computer-generated document which requires no signature. ***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

JENNIFER LEE LIPING

61 MOUNT SINAI DRIVE #14-03

SINGAPORE 277113

Contact : 82339929

ESTIMATE

Repair Code : CLM15207

Date in : 18/03/2021

Vehicle Num. : SMP3350G

Model : TOYOTA HARRIER M GARDE

Chassis/Eng# : JTEZB3GH90J004908/8ARZ165423

REAR TAILGATE INNER TRIM GARNISH <i>new</i>	1	731.35	731.35	<i>+</i>
REAR TAILGATE MECHANISM LOCK <i>new</i>	1	974.00	974.00	<i>+</i>
REAR TAILGATE MECHANISM LOCK COVER <i>new</i>	1	122.40	122.40	<i>✓</i>
REAR TAILGATE WEATHER STRIP <i>cut</i>	1	442.00	442.00	<i>✓</i>
REAR TAILGATE WINDSCREEN MOULDING L/R <i>new</i>	2	7332.50	171.45	342.90 <i>750</i>
REAR TAILGATE WINDSCREEN MOULDING LOWER <i>new</i>	1	5499.37	172.10	122.10 <i>50</i>
REAR TAILGATE WINDSCREEN MOULDING TOP	1	172.10	172.10	122.10 <i>50</i>
REAR TAILLAMP LOWER BRACKET L/R <i>new</i>	2	77.30	154.60	<i>77 154.60 77.30</i>
Subtotal before discount			12,990.50	
Percentage discount 25%			3,247.63	
Sub-total 1			9,742.88	
REAR BUMPER CLIPS - SET <i>new</i>	1	50.00	50.00	<i>30 50.00</i>
REAR END PANEL INNER TOP GARNISH CLIPS - SET <i>new</i>	1	30.00	30.00	<i>+</i> 30.00
REAR RH TAILLAMP CLIPS - SET <i>new</i>	1	30.00	30.00	<i>+</i> 30.00
REAR TAILGATE INNER TRIM GARNISH CLIPS - SET <i>new</i>	1	50.00	50.00	<i>+</i> 50.00
REAR TAILGATE WINDSCREEN SEALANT <i>new</i>	1	80.00	80.00	<i>60 80.00</i>

*** This is a computer-generated document which requires no signature.***

page 2

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

JENNIFER LEE LIPING

61 MOUNT SINAI DRIVE #14-03

SINGAPORE 277113

Contact : 82339929

ESTIMATE

Repair Code : CLM15207

Date in : 18/03/2021

Vehicle Num. : SMP3350G

Model : TOYOTA HARRIER M GARDE

Chassis/Eng# : JTEZB3GH90J004908/8ARZ165423

Subtotal before discount	240.00
Percentage discount 0%	0.00
Sub-total 2	240.00
Parts-total	9,982.88

LABOUR

To reset system after repair works

~~400.00~~ 80

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.

~~100.00~~ 80

To remove, reinstall tailgate windscreen

~~150.00~~ 120

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

~~120.00~~ 60

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

1,000.00 800

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

~~1,000.00~~ 800

To apply anti-rust chemical on repaired and replaced panel.

~~120.00~~ 60

To remove, reinstall tailgate mechanism and check for function

~~80.00~~ ✓**Labour Total****2,970.00****Parts & Labour Total****12,952.88**

*** This is a computer-generated document which requires no signature.***

page 3

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj
h/s 19/03/21
06 Days.

Total: 7669.37

h/s: G.K ✓