

ASS. REC. BY:

REF:

AG/ 210035961kg

Kenneth

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s Tong Luck

of \_\_\_\_\_

Insured: 7782

Policy No. 0999993880

Claims No. 1986317692SG

Sum Insured: \_\_\_\_\_ Excess: 1400

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	<input type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: \$ 70k

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 1-B-1 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: GBH 7276J Yr Regn: 09, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: Mit Car c.c. 2998

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: \_\_\_\_\_ T/Radio: Insured / Std / NI / NA

Eng/No: A

C/No: F9A01BR 25041

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: NI / S/Rim / STD A/Rim or

Tyre Size: F: 185/75R15

R: Yoko \_\_\_\_\_ (D)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / Yoko or \_\_\_\_\_

Front Rear

R/Bal. 7 mm R/Bal. 9 9 mm

L/Bal. 7 mm L/Bal. 9 9 mm

D.O.A. 9/12/20 D.O.I. 19/3/2021

Survey held at ✓

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

FR N/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>1</u>	<u>Battery flat</u>
<u>22/03/21 @ 11.50am</u>	<u>revert to AIG via Merimen.</u>
<u>24/03/21 @ 4.49pm</u>	<u>Kok Chong informed C/A via Merimen.</u>
<u>25/03/21 @ 9.37pm</u>	<u>Informed Candy C/A &amp; ex: \$1400 by email.</u>
	<u>Kenneth confirmed final fig \$4103.84 (Red \$1951.50, 32%)</u>

Date/Time, File Pass to?  : Prell. Report

11/07/05 Typist  : Final Report

Date/Time, File Return to?

2)

Report Format: MER-OD

Lump Sum / I.B.I: (\$) 4103.80

Days Of Repair: 4

Resurvey No. of Trlp: 1

Survey Fee:

Transportation:

Add Fee:  : Site Insp (\$ \_\_\_\_\_) \_\_\_\_\_ \$ - RS. \_\_\_\_\_ \$

: Interview (\$ \_\_\_\_\_) \_\_\_\_\_ \$

: Tech Invs (\$ \_\_\_\_\_) \_\_\_\_\_ \$

: Weekend (\$ \_\_\_\_\_) \_\_\_\_\_ \$

TOTAL



# TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16  
AIG BUILDING  
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 09/12/2020

## ESTIMATE

NO : QUOT202102-000009(00)

DATE : 19/03/2021

POLICY NO : 999995580

VEH REG NO : GBH7276J

MAKE/MODEL : MITSUBISHI CANTER  
FEA01BR2SDEK (CBU)

CHASSIS NO : FEA01BA25041

ENGINE NO : 4P10D25558

REG. DATE : 2018

*Not Authorized*  
*Assembly B4pcim*  
*4 days*

### Estimate Repair Cost to Vehicle No : GBH7276J

Description	Quantity	Unit Price	Amount
		S\$	S\$
<b>PARTS</b>			
1 Headlamp assy - LH	1	SVC 450.00	450.00 <i>car?</i>
2 Signal lamp assy - LH	1	220.00	220.00 <i>Bu</i>
3 Side lamp assy - LH	1	180.00	180.00 <i>Bu</i>
4 Front grille	1	280.00	280.00 <i>CM</i>
5 Front bumper	1	380.00	380.00 <i>Ry</i>
6 Front bumper side - LH	1	250.00	250.00 <i>M/I</i>
7 Front door - LH	1	980.00	980.00 <i>Ry</i>
8 Front door hinges - LH	2	215.00 <i>low</i>	430.00 <i>4</i>
9 Front door ventilator garnish - LH	1	75.00	75.00 <i>CM</i>
10 Front wheel arch garnish - LH	1	78.00	78.00 <i>Bu</i>
			3,323.00
		Add 10%	332.30
			3,655.30
<b>LABOUR</b>			
11 To transfer LH damaged front door interior mechanism and glass to new door	1	120.00	120.00 <i>600</i>
12 To check and rectify wiring system	1	80.00	80.00 <i>200</i>
13 To panel beat and repair LH front door pillar, LH wheel arch panel, including replacement of parts and align where necessary, to refit and adjust the same	1	1,200.00	1,200.00 <i>4000</i>
14 To putty and spray same on affected areas	1	1,000.00	1,000.00 <i>700</i>
			2,400.00
		<b>TOTAL</b>	<b>S\$ 6,055.30</b>
		ADD GST @ 7%	423.87
		<b>GRAND TOTAL</b>	<b>S\$ 6,479.17</b>

SINGAPORE DOLLAR SIX THOUSAND AND FOUR HUNDRED SEVENTY-NINE AND CENTS SEVENTEEN ONLY

- the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission ..... 15/12/2020 15:52 (SGT)  
Date of Accident ..... 09/12/2020 15:00 (SGT)  
Exact Location of Accident ..... Gambas Cres, Singapore  
Additional Location Information ..... ALONG GAMBAS CRESCENT, BESIDE PROXIMA BLDG  
Country/State of Loss ..... Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number ..... GBH7276J

### INSURED/POLICYHOLDER

Is company? ..... Yes  
Name Of Registered Owner ..... DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD  
Company Reg No ..... 1XXXXX778Z  
Email Address ..... faizal.mohamed@daimler.com  
Mobile Phone No ..... (Phone) +65-68498118  
Alternative Phone No ..... (Office) +65-68498118

### VEHICLE PARTICULARS

Manufacturer ..... Mitsubishi  
Model ..... Canter  
Variant ..... -  
Exact purpose for which vehicle was being used at time of accident ..... Private hire  
Are you claiming under your own insurance policy for repair to your vehicle? ..... Yes  
Vehicle Category ..... Commercial vehicle

### INSURANCE COMPANY

Name of Insurance Company ..... AIG  
Type of Coverage ..... Comprehensive  
Fleet Policy ..... Yes  
Policy Number ..... 999995580  
Cover Note Number ..... NA

### DRIVER

Name of Driver ..... MSK DANESSHKUMMARAN A/L MUNUSAMY  
Passport No/FIN ..... AXXXX7521  
Date Of Birth ..... 02/12/1997  
Occupation ..... Outdoor



**ACCIDENT STATEMENT (2000 characters)**

ON THE DATE AND TIME MENTIONED I WAS DRIVING ALONG THE SAID MENTIONED ROAD WHEN I ACCIDENTALLY HIT A STATIONARY VEHICLE B, WHO HAD STOPPED AT THE SIDE OF THE ROAD. NO ONE WAS INJURED.

Taxi Voucher No.:

**DECLARATION**

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -  
HASHIM BIN KAMARI

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

15 December 2020 at 10:01 AM

Date/Time:

15 December 2020 at 10:01 AM