



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

*Not Authorized
Return B4pain*

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

4 days

YOUR REF NO :

19/3/2021

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 09/12/2020

29/3/2021

ESTIMATE

NO : QUOT202102-000009(00)

DATE : 19/03/2021

POLICY NO : 999995580

VEH REG NO : GBH7276J

MAKE/MODEL : MITSUBISHI CANTER
FEA01BR2SDEK (CBU)

CHASSIS NO : FEA01BA25041

ENGINE NO : 4P10D25558

REG. DATE : 2018

Estimate Repair Cost to Vehicle No : GBH7276J

Description	Quantity	Unit Price	Amount
		S\$	S\$
PARTS			
1 Headlamp-assy - LH	1	450.00	450.00
2 Signal lamp assy - LH	1	220.00	220.00
3 Side lamp assy - LH	1	180.00	180.00
4 Front grille	1	280.00	280.00
5 Front bumper	1	380.00	380.00
6 Front bumper side - LH	1	250.00	250.00
7 Front door - LH	1	980.00	980.00
8 Front door hinges - LH	1	215.00	430.00
9 Front door ventilator garnish - LH	1	75.00	75.00
10 Front wheel arch garnish - LH	1	78.00	78.00
			3,323.00
		Add 10%	332.30
			3,655.30
LABOUR			
11 To transfer LH damaged front door interior mechanism and glass to new door	1	120.00	120.00
12 To check and rectify wiring system	1	80.00	80.00
13 To panel beat and repair LH front door pillar, LH wheel arch panel, including replacement of parts and align where necessary, to refit and adjust the same	1	1,200.00	1,200.00
14 To putty and spray same on affected areas	1	1,000.00	1,000.00
			2,400.00
		TOTAL	S\$ 6,055.30
		ADD GST @ 7%	423.87
		GRAND TOTAL	S\$ 6,479.17

*10% \$2,658.00
265.80
\$2,923.80*

lower 1/2 DIY

*600
200
400
700
1180*

SINGAPORE DOLLAR SIX THOUSAND FOUR HUNDRED SEVENTY-NINE AND CENTS SEVENTEEN ONLY

*XS \$4,103.80
1,400.00

\$2,703.80
7% 189.26

\$2,893.06*

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE