

AlGAsia Insured's Veh No : SLU7177A
Date of Accident : 17 March 2021


陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD
1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Messrs Platinum Wines & Spirits Pte Ltd

Date : 19 March 2021

Estimate To Repair GBL137C - Toyota Dyna 150
Chassis No : JTFAT35YX0K216428

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	rear end panel	\$ 385.70
02	1 pc	o/s taillamp	\$ 307.80
03	1 pc	o/s taillamp holder	\$ 99.80
04	1 pc	o/s rear cargo rear door	\$ 998.70
			\$ 1,792.00
		Less 25 %	\$ 448.00
			\$ 1,344.00
		<u>LABOUR & MISC. CHARGES</u>	
01		To check electrical lighting concerned.	\$ 50.00
02		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 500.00
03		Putty and spray painting of the affected portion.	\$ 300.00
			\$ 850.00
		Total	\$ 2,194.00

not allowed
ok
30/8/21
p/p \$ 520
2 days.
Ang He. Aluray

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

begunurus- lkk
30/8/2021 1020h

20
300
200