

JWG INTERNATIONAL PTE. LTD.

10, ANG MO KIO IND PARK 2A, #03-08 AMK AUTOPOINT, SINGAPORE 568047

H/P: 8299 6103 | FAX: 6909 9592

E-Mail: jwg.claims@yahoo.com

To: AIG ASIA PACIFIC INSURANCE PTE LTD

Att: Motor Claims Dept

ACCIDENT INVOLVING SKU7123S [YOUR INSURED] & SJV8726C [OUR CLIENT]
ON 18/03/2021.

ESTIMATED REPAIR COSTS FOR SJV8726C

<u>QTY</u>	<u>PARTS</u>	<u>AMOUNT</u>
1PC	TAILGATE <i>Dent</i> 1141.30	\$ 1,780.50 ✓
1PC	TAILGATE WINDSCREEN MOULDING <i>Hu</i> 112.50	\$ 329.38 ✓
1PC	TAILGATE 'AIRWAVE' EMBLEM <i>Hu</i>	\$ 58.50 ✓
1PC	TAILGATE 'HONDA' EMBLEM <i>Hu</i>	\$ 50.20 ✓
1PC	TAILGATE CENTER CHROME <i>Hu</i>	\$ 498.92 X
1PC	TAILGATE CENTER GARNISH <i>Hu</i>	\$ 651.52 X
2PC	TAILGATE LAMP L+R @ \$445.30 EACH <i>Hu</i>	\$ 890.60 X
2PC	TAILGATE HINGE L+R @ \$106.58 EACH <i>Hu</i>	\$ 213.16 X
2PC	TAILGATE NO. PLATE LAMP L+R @ \$52.80 EACH <i>Hu</i>	\$ 105.60 X
1PC	TAILGATE NO. PLATE LAMP TOP GARNISH <i>Hu</i>	\$ 460.90 X
1PC	TAILGATE INNER TRIM BOARD <i>Hu</i>	\$ 748.30 X
1PC	REAR BUMPER <i>disturb / crack</i> 945.20	\$ 1,378.50 ✓
1PC	REAR BUMPER SPONGE <i>Hu</i>	\$ 310.90 X
2PC	REAR BUMPER SIDE RETAINER L+R @ \$45.00 EACH <i>Hu</i>	\$ 90.00 X
1PC	REAR BUMPER BEAM <i>Hu</i> 1st	\$ 159.20 X ✓
1PC	REAR END PANEL <i>Dent</i> 508.70	\$ 808.72 ✓
1PC	REAR END PANEL TOP GARNISH <i>Hu</i>	\$ 238.54 X
1PC	SPARE WHEEL PANEL <i>Hu</i>	\$ 1,526.82 X
2PC	SPARE WHEEL QUARTER PANEL L+R @ \$980.20 EACH <i>Hu</i>	\$ 1,960.40 X
1PC	SPARE WHEEL PANEL TOP BOARD <i>Hu</i>	\$ 620.39 X
1PC	SPARE WHEEL PANEL TOOL BOX <i>Hu</i>	\$ 498.70 X
2PC	REAR FENDER L+R @ \$1,350.29 EACH <i>Hu</i>	\$ 2,700.58 X
2PC	REAR FENDER INNER TRIM L+R @ \$562.82 EACH <i>Hu</i>	\$ 1,125.64 X
2PC	REAR FENDER QUARTER GLASS MOULDING L+R @ \$849.29 EACH <i>Hu</i>	\$ 1,698.58 X
2PC	TAIL LAMP L+R @ \$496.85 EACH <i>o/s Hu w/s crack mounting</i>	\$ 993.70 ✓
2PC	TAIL LAMP PANEL L+R @ \$189.73 EACH <i>Hu</i> 390.60	\$ 379.46 X
1PC	REAR EXHAUST PIPE <i>Hu</i>	\$ 2,198.00 X
1PC	REAR EXHAUST MOUNTING <i>Hu</i>	\$ 98.00 X
1PC	REAR EXHAUST HEAT SHIELD <i>Hu</i>	\$ 210.00 X

3366.20 PARTS SUM: \$ 22,783.71

2692.96

PARTS LESS 20%: \$ 4,556.74

PARTS TOTAL: \$ 18,226.97

LABOUR & SPECIAL NETT ITEMS

*	TO SUPPLY REAR NUMBER PLATE & CASING H4	\$ 100.00 X
*	TO SUPPLY 1 SET REAR REVERSE SENSOR Dam / dislodged	\$ 300.00 220/-
*	TO SUPPLY 1 PC REVERSE CAMERA H4	\$ 600.00 X
*	TO SUPPLY REAR END PANEL SEALANT H4	\$ 80.00 X
*	TO SUPPLY REAR FENDER SEALANT H4	\$ 80.00 X
*	TO SUPPLY REAR WINDSCREEN SEALANT H4	\$ 80.00 40/-
*	TO SUPPLY REAR WINDSCREEN DAMPING SEAL H4	\$ 30.00 X
*	TO SUPPLY REAR FENDER QUARTER GLASS SEALANT H4	\$ 120.00 X
*	TO SUPPLY REAR FENDER QUARTER GLASS DAMPING SEAL H4	\$ 30.00 X
*	TO SUPPLY TAIL LAMP PANEL SEALANT H4	\$ 80.00 X
*	TO SUPPLY SPARE WHEEL PANEL SEALANT H4	\$ 80.00 X
*	TO SUPPLY TAILGATE CENTER GARNISH CLIPS H4	\$ 50.00 X
*	TO SUPPLY TAILGATE CENTER CHROME CLIPS H4	\$ 50.00 X
*	TO SUPPLY TAILGATE INNER TRIM BOARD CLIPS H4 280.00	\$ 50.00 X
*	TO SUPPLY REAR BUMPER CLIPS H4	\$ 50.00 20/-
*	TO SUPPLY REAR END PANEL TOP GARNISH CLIPS H4	\$ 50.00 X
*	TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILITATE REPAIRS	\$ 300.00 4280/-
*	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	\$ 2,000.00 700/-
*	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	\$ 2,000.00 700/-
*	TO TUFF COAT DAMAGED AREAS	\$ 300.00 40/-
*	TO CONDUCT WATER LEAKAGE TEST	\$ 100.00 H4
*	TO RNR REVERSE CAMERA	\$ 100.00 H4
*	TO RNR REAR FENDER QUARTER GLASS TO FACILITATE REPAIRS	\$ 300.00 H4
*	TO RNR REAR WINDSCREEN TO FACILITATE REPAIRS 1790.00	\$ 400.00 120/-
*	TO RNR TAILGATE MECHANISM TO FACILITATE REPAIRS	\$ 200.00 80/-
*	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	\$ 250.00 H4
*	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	\$ 200.00 30/-
*	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	\$ 300.00 H4
*	TO RNR REVERSE SENSOR TO FACILITATE REPAIRS	\$ 120.00 40/-

LABOUR & S/N TOTAL: \$ 8,400.00

GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 26,626.97

22/03/2021 @ 1050hrs

N/A Actual

L/Sum

4 days.

Man

LKK Auto

4762.96

L/S 3800/-

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: