ASS. REC. BY: REF: AIG!	21003600lkg
	ASSIGNMENT
· TOTAL	(ma 2017) 113 16
Tringrad Cost:	
TO Insper Valida II	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover /
To Inspect Vehicle No:	Truck/Trailer or
at Workshop m/s	Make: Mc 5400 c.c 2446
of lang look	
Insured:	Sp.Reading 101772 T/Radio: Insured / Std / NI / NA
Policy No. 999993670	Eng/No:
Claims No. 5439612118SG ,	CNO: WOO 2221652A225764
Sum Insurade	Gen. Cond: Good / Fair / Poor / Burnt
(Client's Record)	Sleering: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Brake: Inorder/Jammed/Leaked/Burnt or
	Modi: Nil / S/Rim / STE ARim or
(Policy Condition)	Tyre Size: F: 245/45R19
Remark: The year had as	R: 275/40R19
repair at the time of inspection.	BSTOUNTEXNOVATGYTESTLIZATMICTOHTSU PFIR SUMIT
Bal. or Market Value: 8 210k	TOYO/YOKO or
IDAC Accident Rport: Consistent?: Yes or No	Fron! P Rear
GIA / PR Seen: Consistent?: Yes or No	R/Bal. 0 mm R/Bal. 5 mm
Est Repairs: Of days Res.: Yes or No	UBal. mm UBal. 5 mm
Lum Sum: /-B./ % 3 Val.: Yes or No	0.0.A. 8/3/21 D.O.I. 19/3/202
	Survey held at
CA / REV / REP. / 24 HRS Vehicle: IN / OI	Des. of Darnages Frt Rear O/S N/S U/C Rooftop or
Date:Person Contacted:	
Date / Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.
22 <u>/03/21@11.50am revert to AIG via Merimen</u>	
22/03/21@3.34pm Kok Chong informed C/A via	
22/03/21@4.48pm Informed Candy C/A & ex:\$	· · · · · · · · · · · · · · · · · · ·
Kenneth confirmed final fig \$8769.	30 (Red \$1139.75, 12%)
1779-987	
Data/Time, File Pass to? : Prell. Report	Days Of Repair: 4
1)21/06 Typist : Final Report	Resurvey No. of Trip: 1 Survey Fee:
Outo/Fime, File Return 107	Transportation:
Add Fe	96: : Site Insp (\$)s-Rssi
	Interview (\$
Report Format: MER-OD	Tech Inve (S
Lump Sum/ I.B.I: (\$ 8769.30	Weekend (S
	· · · · · · · · · · · · · · · · · · ·
A transfer of the second secon	107AL



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545 Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

: AIG ASIA PACIFIC INSURANCE PTE. LTD.

: OWN DAMAGE

78 SHENTON WAY #07-16

AIG BUILDING

SINGAPORE 079120

ATTN: MOTOR CLAIM DEPT

ACCIDENT DATE : 08/03/2021

TEL : 6419 3000

YOUR REF NO

CLAIM TYPE

FAX: 6415 3723

ESTIMATE NO

: QUOT202103-000025(00)

: 19/03/2021 DATE : 999995580 POLICY NO VEH REG NO : SMD3827L

MAKE/MODEL: MERCEDES BENZ S400L (R19

LED)

: WDD2221652A225764 **CHASSIS NO**

: 27682430300477 **ENGINE NO**

: 2016 REG. DATE

Estimate Repair Cost to Vehicle No: SMD3827L

	Description		Quantity	Unit Price	Amount
				<u>s\$</u>	<u>s</u> \$
	PARTS			580.00	CM 580.00
	Support panel		1	Bulke 1,120.00	1,120.00
	Front bumper		1		480.00
3	Front bumper reinforcement		1	480.00	
4	Front bumper sponge		1	185.00	276.00
5	Front bumper sensor		2	138.00	48.00
6	Front bumper sensor seals		6	8.00	
7	Front bumper clips	# ** ** ** ** ** ** ** ** ** ** ** ** **	15	6.50	37.00
8	Front bumper center grille		1	98.00	00.00
9	Front number plate garnish .		1	108.00 CM 3.300.00	C.E. Markey, Mr. Consequence
	Headlamp assy - LH	LKK Auto Consultants hence notify		0,000.00	3,300.00
	Front grille assy	the Repairer of the following: To resurvey before/after spray painting	1	550.00	
	Air duct	To display damaged part(s) during resurvey	1	118.00	118.00
13	Air guide - LH	 Parts prices are subject to confirmation 	1	75.00	CM 75.00
		 Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed 	s	A 4 000	7,035.50
		Supplementary item(s) must be resurveyed and		Add 10%	
	SPECIAL NET	is subject to final approval from Insurance Compan	у		7,739.05
14	Front number plate	Acknowledged by Repairer	1	40.00	By 40.00
	Tollerania Pinto	Signature:			40.00
	LABOUR	Date:			40.00
15	To remove and refit air-con cor	denser, radiator and refill air-con	1	150.00	150.00
40	gas	concer		100.00	400.00
	To remove & refit front bumper			100.00	100.00
17	To check and rectify witing sys		1	80.00	80.00
18	To panel beat and straighten from the panel beat and straighten from the parts and align	where necesary, to refit and adjust		1,000.00	1,000.00
	the same				. 6
19	To putty and spray paint on affected areas		1	800.00	800.00
		**			2,130.00
				TOTAL	S\$ 9,909.05
				ADD GST @ 7%	693.63
				GRAND TOTAL	S\$ 10,602,68

SINGAPORE DOLLAR TEN THOUSAND SIX HUNDRED TWO AND CENTS SIXTY-EIGHT ONLY

SA0A21380007 / Ajax Mars Pte Ltd ENTRY DATE & TIME: 08/03/2021 15:23 (SGT) SUBMITTED BY: Meilin VERSION: 1 (08/03/2021 15:23 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report <u>correctly</u> the details of the accident to speed up the claims process.
2. This Form must be <u>completed by the Policyholder and/or the Authorised Driver</u>
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate Delicy liability
 Any false rappoints may be afforded to the Ballos for investigation

In e issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the policy insurance companies.
 Any false reporting may be referred to the Police for investigation.
 This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
 By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 08/03/2021 15:23 (SGT) Date of Accident 08/03/2021 09:15 (SGT) **Exact Location of Accident** Singapore Additional Location Information PIE TOWARDS TUAS NEAR EXIT 33 Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMD3827L

INSURED/POLICYHOLDER

Is company? Yes Name Of Registered Owner DAIMLER FLEET MANAGEMENT SINGAPORE PTE, LTD Company Reg No 1XXXXXX78Z **Email Address** derrick.lee@daimler.com Mobile Phone No (Phone) +65-82821711 Alternative Phone No +65-82821711

VEHICLE PARTICULARS

Manufacturer Mercedes Model S400L (R19 LED) Exact purpose for which vehicle was being used at time of Private use accident Are you claiming under your own insurance policy for repair to Yes your vehicle? market and the second s Vehicle Category Private car

INSURANCE COMPANY

Name of Insurance Company AIG Type of Coverage Comprehensive Fleet Policy Yes **Policy Number** 999995580 Cover Note Number


DRIVER

Name of Driver ALEX LEE KOK SENG NRIC No SXXXX220J Date Of Birth 25/01/1964 Occupation Indoor



Page 1 of 18





Vehicle A. SMD 3827L Vehicle B: SKW9647Z Vehicle: SMM1867L

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO ATT	ACHED STATEM	NT.		, A.	4	
		PE COLONS	32 -21 p2			
				2.4.1		
, p =	Programme Tollage					
				Para di	A R. 195	
		Carlo Straig				
		F 62- 12-		Alto Alto	retard to give	· 1 · · · · · · · · · · · · · · · · · ·
Jan 1 10				-		
Y				-		
4 - 45 22	e e			And off read of		
etter som a	we firm in	27/10/10/17	a semi-	e de la		
THE STATE OF THE S						
Tag the second of		ty and the second	5-22-1-433	s with s	WING I BY	and the feeting of the
N. H. P.			3-3-1	44	and the second s	
A2 3					en Mariana	
				4		
742	ADVE TO	ta Arresta de la			TO SERVER	TO THE REAL PROPERTY.
	The same of the same	is the second		A Park	**	7.27

DECLARATION

I/We declare the foregoing particulars are true in every respect,

Policyholder's Signature Date & Time: Oriver's Signature

(If driver is not the policyholder)

Date & Time:

VERIFY BY AJAX MARS (ARC)
REPORTING OFFICER
MOHAMED SAIFULIAH 5/O SYED MASOOD

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

2