



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16

AIG BUILDING

SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 08/03/2021

ESTIMATE

NO : QUOT202103-000025(00)

DATE : 19/03/2021

POLICY NO : 999995580

VEH REG NO : SMD3827L

MAKE/MODEL : MERCEDES BENZ S400L (R19 LED)

CHASSIS NO : WDD2221652A225764

ENGINE NO : 27682430300477

REG. DATE : 2016

Estimate Repair Cost to Vehicle No : SMD3827L

Description	Quantity	Unit Price	Amount
		S\$	S\$
PARTS			
1 Support panel	1	580.00	580.00
2 Front bumper	1	1,120.00	1,120.00
3 Front bumper reinforcement	1	480.00	480.00
4 Front bumper sponge	1	185.00	185.00
5 Front bumper sensor	2	138.00	276.00
6 Front bumper sensor seals	6	8.00	48.00
7 Front bumper clips	15	6.50	97.50
8 Front bumper center grille	1	98.00	98.00
9 Front number plate garnish	1	108.00	108.00
10 Headlamp assy - LH	1	3,300.00	3,300.00
11 Front grille assy	1	550.00	550.00
12 Air duct	1	118.00	118.00
13 Air guide - LH	1	75.00	75.00
			7,035.50
		Add 10%	703.55
			7,739.05
SPECIAL NET			
14 Front number plate	1	40.00	40.00
			40.00
LABOUR			
15 To remove and refit air-con condenser, radiator and refill air-con gas	1	150.00	150.00
16 To remove & refit front bumper sensor	1	100.00	100.00
17 To check and rectify wiring system	1	80.00	80.00
18 To panel beat and straighten front chassis frame, including replacement of parts and align where necessary, to refit and adjust the same	1	1,000.00	1,000.00
19 To putty and spray paint on affected areas	1	800.00	800.00
			2,130.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary benefit must be reviewed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

TOTAL S\$ 9,909.05

ADD GST @ 7% 693.63

GRAND TOTAL S\$ 10,602.68

SINGAPORE DOLLAR TEN THOUSAND SIX HUNDRED TWO AND CENTS SIXTY-EIGHT ONLY