

1104 Justin



TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Asia Insured's Veh No : SME4370A
Date of Accident : 18 March 2021

Messrs Citi-Lux Pte Ltd

Date : 18 March 2021

not Affected

here

19/3/21

P/P #2278.56

3 days

Zhe zhe Behu party.

Luk - Marcus

14/03/2021 00:30 hr

Estimate To Repair SMP6368L - Hyundai AD Avente 1.6 GLS (A) S
Chassis No : KMHD841CMKU916757

S/No	Quantity	Description	Amount
LIST ITEMS			
01	1 pc	bootlid weatherstrip 11	\$ 251.00
02	1 pc	bootlid S badge 11	\$ 59.00
03	1 pc	bootlid centre emblem badge 11	\$ 54.00
04	1 pc	bootlid Avente badge 11	\$ 51.00
05	1 pc	bootlid drain plug 11	\$ 36.00
06	1 pc	bootlid lock top 11	\$ 116.00
07	1 pc	bootlid lamp o/s 11	\$ 286.00
08	1 pc	rear lamp o/s 11	\$ 307.00
09	1 pc	rear bumper 32	\$ 659.00
10	1 pc	rear bumper lower 32	\$ 350.00
11	2 ps	rear bumper side retainer @ \$44.00 11	\$ 88.00
12	2 ps	rear bumper reflector @ \$41.00 51	\$ 82.00
13	1 pc	rear bumper reinforcement 11	\$ 350.00
14	1 pc	rear bumper lower splash cover 11	\$ 82.00
15	1 pc	rear bumper lower splash cover clips 11	\$ 36.00
16	1 pc	rear bumper side bracket 11	\$ 176.00
17	1 pc	rear bumper top bracket 11	\$ 50.00
18	1 pc	rear end panel R	\$ 379.00
19	1 pc	rear end panel inner trim 11	\$ 59.00
20	6 ps	rear end panel inner trim clips @ \$3.50 11	\$ 21.00
Less 20 %			\$ 3,492.00
			\$ 698.40
			\$ 2,793.60
SPECIAL NETT ITEMS			
21	1 pc	rear licence plate 51	\$ 80.00
22	1 set	rear bumper reverse sensor 51	\$ 350.00
			\$ 430.00
LABOUR & MISC. CHARGES			
01		To transfer of bootlid fittings, attachments and perform water seepage test.	\$ 11 100.00
02		To rust-proofing of the affected areas.	\$ 11 180.00
03		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 100.00
04		To check electrical lighting concerned.	\$ 60.00
05		To reinstall of rear bumper parking sensor.	\$ 150.00
06		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 950.00

598.20

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

40

200

200

200

200

200

200

200

200

200

200

200

200



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Asia Insured's Veh No : SME4370A
Date of Accident : 18 March 2021

Messrs Citi-Lux Pte Ltd

Date : 18 March 2021

Estimate To Repair SMP6368L - Hyundai AD Avente 1.6 GLS (A) S
Chassis No : KMHD841CMKU916757

S/No	Quantity	Description	Amount
07		LABOUR & MISC. CHARGES	
		Putty and spray painting of the affected portion.	\$ 1,000.00
			\$ 2,540.00
		Total	\$ 5,763.60

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey / before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature:
Date:

P - 1298.2
202
P - 1038.5
SW 240
L 1000
2278.5