

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0225/2021/HR
DATE : 17-Mar-21
WIP : 19807

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 19/3/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR. LOH KHENG HENG
ADDRESS : 207 COMPASSVALE LANE
#15-40
SINGAPORE 640980
TELEPHONE : HP +65 97477119
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070165132
VEHICLE NO : **SFQ 3533 Z**
MODEL CODE : Q3 1.4 TFSI S TRONIC
MODEL YEAR : 27/11/2020
ENGINE NO : CZD C11290
CHASSIS NO : WAUZZZF39M1029061
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 12-Mar-21
PLACE OF ACCIDENT : NEAR BUANGOK DRIVE

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SFQ 3533 Z

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	✗
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,400.00	500
4	TO RESPRAY FRONT BUMPER & RHS FRONT FENDER.	\$ 2,500.00	550
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 5,972.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFQ 3533 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Regis</i>	1	\$ 1,008.00	X
2	FRONT BUMPER CONNECTING PIECE <i>Neu</i>	1	\$ 145.00	X
3	FRONT BUMPER CLOSING ELEMENT - LH <i>Neu</i>	2	\$ 59.00	X
4	FRONT BUMPER LOWER GRILLE LONG - CENTER <i>Neu</i>	1	\$ 217.00	X
5	FRONT BUMPER LOWER GRILLE COVER <i>Neu</i>	1	\$ 51.00	X
6	FRONT BUMPER LOWER GRILLE SHORT - LH <i>Neu</i>	1	\$ 110.00	X
7	FRONT BUMPER CLOSING ELEMENT LOWER <i>Neu</i>	1	\$ 190.00	X
8	FRONT BUMPER SPOILER <i>Neu</i>	1	\$ 383.00	X
9	FRONT BUMPER SPOILER BRACKET <i>Neu</i>	1	\$ 21.00	X
10	FRONT BUMPER AIR GUIDE GRILLE - LH <i>Neu</i>	1	\$ 153.00	X
11	RADIATOR GRILLE <i>Canal d</i>	1	\$ 1,433.00	✓
12	RADIATOR GRILLE STRICKER PLATE ?	1	\$ 244.00	?
13	RADIATOR GRILLE BRACKET ?	1	\$ 41.00	?
14	FRONT BUMPER FOAM FILLER PIECE <i>Neu</i>	1	\$ 102.00	X
15	FRONT BUMPER CARRIER <i>Neu</i>	1	\$ 916.00	X
16	FRONT BUMPER COVER <i>Neu</i>	1	\$ 123.00	X
17	FRONT BUMPER GUIDE SECTION - LH <i>Neu</i>	1	\$ 38.00	X
18	"CAUTION" LABEL <i>Neu</i>	1	\$ 14.00	X
19	AIR CONDITIONER STICKER <i>Neu</i>	1	\$ 8.00	X
20	FRONT PARKING AID SENSOR <i>Neu</i>	1	\$ 244.00	X
SUB TOTAL SPARE PARTS		:	\$ 5,500.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFQ 3533 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT PARKING AID SENSOR SEAL RING <i>Not in</i>	1	\$ 14.00	+
22	HIGH TONE HORN - LH <i>Not in</i>	1	\$ 137.00	+
23	HIGH TONE HORN SPRING SHACKLE - LH <i>Not in</i>	1	\$ 22.00	+
24	FRONT FENDER - LH <i>Not in</i>	1	\$ 1,286.00	+
25	FRONT FENDER ATTACHMENT PARTS - LH <i>Not in</i>	1	\$ 63.00	+
26	FRONT FENDER BRACE - LH	1	\$ 88.00	✓
27	FRONT FENDER BRACKET - LH <i>Not in</i>	1	\$ 32.00	+
28	HEADLIGHT MOUNTING - LH	1	\$ 118.00	+
29	LED HEADLIGHT - LH <i>Not in</i>	1	\$ 5,589.00	+
30	HEADLIGHT LIFT CYLINDER - LH <i>Not in</i>	1	\$ 210.00	+
31	FRONT WHEEL COVER - LH / RH <i>Not in</i>	1	\$ 536.00	✓
32	LOCK CARRIER AIR GUIDE - LH <i>Not in</i>	1	\$ 38.00	+
33	LOCK CARRIER AIR GUIDE - LOWER CENTER <i>Not in</i>	1	\$ 84.00	+
34	FRONT NUMBER PLATE <i>Best</i>	S/N	\$ 60.00	✓
35	SUNDRIES		\$ 250.00	?
TOTAL SPARE PARTS		:	\$ 14,027.00	
TOTAL LABOUR CHARGES		:	\$ 5,972.00	
GRAND TOTAL		:	\$ 19,999.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian*
SURVEYED DATE : *19/03/21*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 03 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: