

Section A - Accident Details

Registration Number	SHD6447P
Case Reference Number	TAX/03/21/2054
Registration Date	3/11/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	AZIMI BIN ATTAN
Type of Accident	Head to Rear
Accident Date and Time	16/3/2021 12:47 PM
Accident Reported Date and Time	16/3/2021 3:10 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24110097
Special Instruction to ARC, if any	TP /REAR PORTION / NTUC - LKK
Prepared Date and Time	17/3/2021 11:17 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$507.00	\$200.00
Total Spray Cost	\$1,098.00	\$200.00
Total Spare Part Cost	\$5,590.61	\$1,069.96
Total Other Cost	\$480.00	(\$269.96)
TOTAL COST	\$7,675.61	\$1,200.00 (L/S)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	3.0
Prepared / Adjusted By	Ang Bang Kien	Sun Pin (LKK) / NTUC
ARC / Surveyor Sign Off Date	19/03/2021 11:10 AM	19/03/2021 11:04 AM
Signature		
Remarks	Total number of repair days = 3 days. SUP =+1 day.	L/S, after paint photo.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2104-0033	Invoice Number	
Quotation Date	06.04.2021	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$507.00	\$200.00 ✓
Total Labour	\$507.00	\$200.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00 ✓
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY FILLER RR BUMPER LH	\$180.00	\$0.00
TO RESPRAY FILLER RR BUMPER RH	\$180.00	\$0.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$1,098.00	\$200.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO TRANSFER REAR TAILGATE MECHANISM	\$120.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$30.00 ✓
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00 ✓
TO WASH AND VACUUM	\$60.00	\$0.00
Lump Sum Adjustment by Surveyor	\$0.00	(\$319.96)
Total Other Costs	\$480.00	(\$269.96)

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52462470 30	PAD, RR BUMPER, RH & LH , 1	2.00	\$3.80	25.00	\$5.70	Replace	Replace
		52462470 20	PAD, RR BUMPER, RH & LH , 2	2.00	\$3.80	25.00	\$5.70	Replace	Replace
		52462470 10	PAD, RR BUMPER, RH & LH , 3	2.00	\$3.80	25.00	\$5.70	Replace	Replace
		52461470 10	PAD, RR BUMPER, CTR	3.00	\$2.20	25.00	\$4.95	Replace	Replace
		52191470 30	SEAL, RR BUMPER ARM, RH & LH	0.00	\$11.00	0.00	\$0.00	Replace	Not Given
		52575470 40	RETAINER, RR BUMPER, RH	0.00	\$112.70	0.00	\$0.00	Replace	Not Given
		52576470 40	RETAINER, RR BUMPER, LH	0.00	\$111.50	0.00	\$0.00	Replace	Not Given
		52591470 50	SEAL, RR BUMPER , RH	0.00	\$85.20	0.00	\$0.00	Replace	Not Given
		52592470 40	SEAL, RR BUMPER , LH	0.00	\$85.20	0.00	\$0.00	Replace	Not Given
		52161160 10	CLIPS PIECE, FRT & RR BUMPER	10.00	\$1.50	25.00	\$11.25	Replace	Replace
		52453470 10	GUARD, RR BUMPER, LOWER	0.00	\$558.30	0.00	\$0.00	Replace	Not Given
		52565479 00	FILLER, RR BUMPER , RH	0.00	\$119.90	0.00	\$0.00	Replace	Not Given
		52566479 00	FILLER, RR BUMPER , LH	0.00	\$119.90	0.00	\$0.00	Replace	Not Given

NEC
NEC
NEC
NEC

} SVC

NEC

} SVC

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 06/04/2021

User ID : PohSuan

	5216947020	COVER, GUARD RR BUMPER LOWER	0.00	\$14.80	0.00	\$0.00	Replace	Not Given	X
		PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace	
		SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	Replace	
	8999730100	ANTENNA, ELECTRICAL KEY	0.00	\$60.30	0.00	\$0.00	Replace	Not Given	X
	8155147281	LENS & BODY, REAR COMBINATION LAMP, RH	0.00	\$438.10	0.00	\$0.00	Replace	Not Given	X
	8156147151	LENS & BODY, REAR COMBINATION LAMP, LH	0.00	\$438.10	0.00	\$0.00	Replace	Not Given	X
	8158147010	LENS & BODY ASSY, RR BUMPER, RH	0.00	\$486.80	0.00	\$0.00	Replace	Not Given	X
	8159147010	LENS & BODY ASSY, RR BUMPER, LH	1.00	\$486.80	100.00	\$0.00	Replace	Old Damage	X
	5839847050	COVER, REAR FLOOR UNDER, RH	0.00	\$169.50	0.00	\$0.00	Replace	Not Given	X
	5839947030	COVER, REAR FLOOR UNDER, LH	0.00	\$234.30	0.00	\$0.00	Replace	Not Given	X
	6625947010	COVER, REAR FLOOR UNDER CENTER	0.00	\$222.60	0.00	\$0.00	Replace	Not Given	X
	7680147110A1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-	0.00	\$891.20	0.00	\$0.00	Replace	Not Given	X
	7544147090	NAME PLATE (HYBRID), LUGGAGE COMPARTMENT	0.00	\$52.30	0.00	\$0.00	Replace	Not Given	X
	7544247130	NAME PLATE (PRIUS), LUGGAGE COMPARTMENT	0.00	\$52.30	0.00	\$0.00	Replace	Not Given	X
		SMRT LOGO	0.00	\$7.80	0.00	\$0.00	Replace	Not Given	X
		STICKER DECAL 6555 8888	0.00	\$21.60	0.00	\$0.00	Replace	Not Given	X
	5202347030	REAR BUMPER REINFORCEMENT	0.00	\$318.80	0.00	\$0.00	Replace	Check	X
	5215947913	COVER, RR BUMPER ASSY	1.00	\$423.90	25.00	\$317.93	Replace	Replace	
Total				\$5,778.00		\$651.23			

SVC
Nec short
SVC
SVC
Def

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		5245347010	GUARD, RR BUMPER, LOWER	1.00	\$558.30	25.00	\$418.73	Replace	Replace
		8155147281	LENS & BODY, REAR COMBINATION LAMP, RH	0.00	\$438.10	0.00	\$0.00	Replace	Not Given
Total					996.40		418.73		

CRU
SVC

1069.96 ✓
+ 200.00 ✓
+ 250.00 ✓
1519.96 ✓
- 20%
1215.97 ✓
45 \$1,200 ✓
3 days
SHD 6447P