



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CS/FCI21003612/T1vd3e2	
			Date: 14/06/2021	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SBS 6520C	Veh. Inspected	SBS 6811M	
Policy No.	D-19094111MFBP	Coverage (\$)	0.00	
Claim No.	D21000858MFBP	Excess (\$)	0.00	
Assign From	JACLYN KESAVAL	Assign Date	19/03/2021	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ CITARO	c.c	6374	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	WEB62808323125480	Colour	MULTI COLOUR	
Odometer	564656 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	275/70 R22.5	BRIDGESTONE	8 mm	
L/H Front Tyre	275/70 R22.5	BRIDGESTONE	8 mm	
R/H Rear Tyre	275/70 R22.5 (D)	BRIDGESTONE	8/8 mm	
L/H Rear Tyre	275/70 R22.5 (D)	BRIDGESTONE	8/8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/02/2021	Inspection Date	22/03/2021	
Survey held at	SBS TRANSIT LTD (Branch) BEDOK NORTH DEPOT 1470 BEDOK NORTH AVE 4 SINGAPORE 489946			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			1 Working Days	