



SBS6811M - rear portion (POI)

When I was resting in BND, OCC called me to inform that the GAS bus SBS6520C svc 3 LH view mirror had hit my bus rear at the egress of TMI on that day. I was not aware of it at that time. According to OCC, the svc 3 BC forgot to pull his handbrake & as a result its LH view mirror had hit my bus rear which I checked there was no visible damage. At that time, I was informed by the 3P. No injury. That's all.



Thanks regards,
Muru
Interchange Supervisor
Tampines Interchange
Tel: 67889120

Accident Reference & Bus No: E/1042/2021 - SBS6811M

Activated date: Wednesday, March 17, 2021 11:00 AM

Activated by: Norlela Binte Ahmad Yusoff <norlelabay@sbstransit.com.sg>

Estimate for

- ☐ Parts cost: \$ 0
- ☐ Contractor Labour cost: \$ 480 +gst To repair rear LH PORTION - \$480
- ☐ Repair period: 1 day
-

