



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21003615/T1Uqd3n2	
			Date: 29/09/2021	
			Code: SMO	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	GBA 3983P		Veh. Inspected	SJV 187K
Policy No.			Coverage (\$)	0.00
Claim No.	CMTD2100807/GPL		Excess (\$)	0.00
Assign From	GRACE TEO		Assign Date	19/03/2021
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	AUDI A6		c.c	1984
Engine No.	HIDDEN		Year of Reg.	2008
Chassis No.	WAUZZZ4F88N156900		Colour	BLACK
Odometer	118633 KM		Steering	IN ORDER
Brakes	IN ORDER		Modification	SPORTS RIM
General	GOOD			
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
R/H Front Tyre		245/40 R18	PIRELLI	6 mm
L/H Front Tyre		245/40 R18	PIRELLI	6 mm
R/H Rear Tyre		245/40 R18	PIRELLI	6 mm
L/H Rear Tyre		245/40 R18	PIRELLI	6 mm
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	12/03/2021		Inspection Date	24/03/2021
Survey held at	56 LOYANG WAY # 04-04			
Repairer	AP AUTOMOTIVE SERVICES PTE LTD			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>3 Working Days</b>	