

Estimation

Date 20/3/2021
 Vehicle SJV 187K
 Make/Model AUDI A6
 Chassis No. WAUZZZ4F88N156900

No.	Description	Unit	Unit Price	Amount
	Parts Replacment	1		
1	FRONT BONNET <i>X R</i>	1		\$ -
2	FRONT BONNET INNER TRIM <i>X nn</i>	1		\$ -
3	FRONT BONNET LOCK <i>X nn</i>	1		\$ -
4	FRONT HEADLAMP L+R <i>X cr</i>	2	\$1,700	\$ 3,400.00
5	FRONT HEADLAMP BRACKET L+R <i>X nn</i>	2		\$ -
6	FRONT GRILLE <i>cr</i>	1		\$ 597.00
7	FRONT GRILLE CHOME <i>cr</i>	1		\$ 275.50
8	FRONT GRILLE LOGO <i>nn</i>	1		\$ 86.70
9	FRONT BUMPER <i>de</i>	1		\$ 2,347.00
10	FRONT BUMPER LOWER CHROME L+R <i>X nn</i>	2		\$ -
11	FRONT BUMPER FOG LAMP GARNISH L+R <i>nn</i>	2		\$ -
12	FRONT BUMPER FOG LAMP L+R <i>cr</i>	2	\$228.00	\$ 456.00
13	FRONT BUMPER RETAINER L+R <i>nn</i>	2	\$136.00	\$ 272.00
14	FRONT BUMPER BRACKET L+R <i>X nn</i>	2		\$ -
15	FRONT BUMPER HEADLAMP NOZZLE L+R <i>X nn</i>	2		\$ -
16	FRONT BUMPER REINFORCMENT BAR <i>X nn</i>	1		\$ -
17	FRONT BUMPER SPONGE <i>X nn</i>	1		\$ -
18	FRONT BUMPER SENSOR <i>X nn</i>	SET		\$ -
19	FRONT FENDER L+R <i>X nn</i>	1		\$ -
20	FRONT FENDER COWLING L+R <i>X nn</i>	1		\$ -
21	FRONT SUPPORT PANEL <i>X nn</i>	1		\$ -
22	FRONT SUPPORT PANEL TOP GARNISH <i>de</i>	1	\$316.00	\$ 316.00
23	FRONT HORN <i>X nn</i>	2		\$ -
24	FRONT BRACEPANEL	1		\$ -
	7750.20			7750.20
	6975.18			
		Total		\$ 6975.18
		Less 10%		\$ -
		Total		\$ -

S/Nett Items					
1	FRONT BONNET INNER TRIM CLIPS	SET	120	\$ <i>X nn</i>	120.00
2	FRONT BUMPER CLIPS	SET	120	\$ <i>30 nn</i>	120.00
3	FRONT SUPPORT PANEL TOP GARNISH CLIPS	SET	120	\$ <i>10 nn</i>	120.00
4	FRONT FENDER COWLING CLIPS	SET	120	\$ <i>X nn</i>	120.00

			Total	\$ 480.00

LABOUR				
1	PANEL BEATING ON AFFECTED AREAS	1	1000	\$ 300 1,000.00
2	SPRAY PAINT ON AFFECTED AREAS	1	1000	\$ 100 1,000.00
3	TO CHECK WIRING AND HEADLAMP FOCUS	1		30. #VALUE! 60
4	TO RNR FRONT AIR CON CONDENSOR AND TOP UP GAS	1	250	\$ 30 250.00
5	TO RNR FRONT RADIATOR	1	250	\$ X UN 250.00
6	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	1	400	\$ 100 400.00
7	TO RNR HORN AND TEST FUNCTION	1	120	\$ X UN 120.00
Total Labour				#VALUE! 3020
Parts Replacement Amount				\$ 480.00
Total Amount				#VALUE!

~~860~~
860

Taughin 97495749
 WP 24/3/21 @ 3pm.
 03 days
 c/s Resurvey after repair
 Taughin @ Kuantan

P = \$ 7,750.20
 - 10% = \$ 6,975.18
 SN = \$ 40 ✓
 L = \$ 860 ✓
 7 = \$ 7875.18
 - 20% = \$ 6,300 ✓

6975.18
 40
 860

7875.18
 45 \$ 6300
 03 days #

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: