

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
10 Eunos Road 8, #09-04A Singapore Post Centre
Singapore 408600

Our File No: CS4/ICS21003618/NQD3E2

Date: 28/04/2021

REFERENCE

Insured/Claimant: MARC HO KERK TZE Policy No: MPC21P00012500
Date of Loss: 17/03/2021 Nature of Claim: OD Claim No: DMPC2100093H/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKK4937H**
Make & Model: MINI COOPER, 1.6 COUNTRYMAN HB 5 SEATER Engine No: A870J280N16B16A
DSC ABS (A)
Reg. Date: 24/07/2013 (Man. Year: 2012) Chassis No: WMWZB32010WL93954
Colour: Grey Odometer: 0 km
Engine Capacity: 1598 cc
Market Value/New Car Price: S\$52,000.00
Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: Rear Tyre Size:
Front Left Side: 0 mm Rear Left Side: 0 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	0.00	0.00	0.00	
- Excess (\$\$)	1,500.00	1,500.00	0.00	0.00
Nett Amount (\$\$)	-1,500.00	-1,500.00	0.00	0.00

INSPECTION

Date of Assignment: 19/03/2021

Date Inspected: 22/03/2021 Inspected At:

Estimated Period of Repair: 0.0 days

BH Auto Services Pte Ltd (Sin Ming)
Blk 1 Sin Ming Industrial Estate Sector C,
#01/111/113/115/117
Singapore 575636

Adjuster: Muhammad Nazril Bin Abdullah

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

TOTAL LOSS ASPECT

Market Value :	\$52,000.00
OMV :	\$26,737.00
PARF Rebate (1) :	\$17,659.00
Quota Premium Paid :	\$73,100.00
COE Rebate (2) :	\$17,021.00
Total Rebate (1) + (2) = :	\$34,680.00

The total amount incurred will be Market Value \$52,000.00 minus Total Rebate \$34,680.00 = \$17,320.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference		
Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 Apr 2021)		
Parts:	144	MINI COOPER 1.6 COUNTRYMAN HB 5 SEATER DSC ABS (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's (Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SKK4937H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >