

LCRF PTE LTD  
CARROS CENTER  
60 JALAN LAM HUAT #04-01 S(737869)  
Main +65 62524991

Ms China Taiping Insurance  
Date 19/03/2021  
Attn : MOTOR CLAIMS DEPT

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

### ESTIMATE

VEHICLE NO. SLM8826X  
Chassis No: JM6BN22A8H0149327  
MAKE / MODEL : Mazda 3 Sedan 1.5 AT  
DATE OF ACCIDENT : 07/03/2021  
YOUR INSURED VEHICLE NUMBER :SJJ5992H  
MILEAGE : 233866 km

PARTS DESCRIPTION	QTY	UNIT PRICE	LIST PRICE
1 Rear bumper / CRU	1PC	\$1,129.00	\$1,129.00 ✓
2 Rear bumper lower cover X <sup>svc</sup>	1PC	\$300.00	\$300.00 ✓
3 Rear bumper reinforcement 2 X <sup>svc</sup>	1PC	\$564.20	\$564.20 X
4 Rear bumper LH tow cover / CRU	1PC	\$40.00	\$40.00 ✓
			\$1,993.20 1,169
		20% DISCOUNT S\$:	\$398.64 -20%
			\$1,594.56 935.20
<b>S/Nett</b>			
1 Rear Bumper clips / Net		\$100.00	30
2 Reverse sensor / short		\$240.00	200
	Total	\$340.00	230.

<u>LABOUR CHARGES</u>			
1	To labour charge for removing out rear boot, rear bumper and end panel out to facilitate repairs and replacement of damaged parts.	\$700.00	250
2	To respray rear bumper, rear bumper tow hook cover	\$380.00	250.
	LABOUR TOTAL S\$:	\$1,080.00	500
	TOTAL S\$:	\$3,014.56	
	7% GST	\$211.02	
	GRAND TOTAL S\$:	\$3,225.58	

Repair day - 2 days  
P/P  
begin pain phuu  
Sun pin CL(uc)  
22/03/2021  
TP with prgm

935.20  
230  
500  
1,665.20