

# CN MOTORS PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-41 Autobay@Kaki Bukit, Singapore 417883

Email: admin@cnmotorspl.com

Tel: 6509 5545 Fax: 6509 5567

UEN: 202026492W GST Reg No: 202026492W

Blk 1 Kaki Bukit Ave 6  
# 01-43  
Singapore 417883

22/03/2021

TP AXA  
Ceilia

Accident date: 19/03/2021

Estimated repair cost for vehicle no: SLP7702K AUDI A8L 3.0 TFSI QU 17'

CHASSIS: WAUZZZ4H7FN007750

S/n	Qty	Items	U/price	Amount
1	1	Front Bonnet <i>Distorted.</i>		\$6645 ✓
2	2	Front Bonnet Hinge <i>New</i>	\$202.35	\$404.70 ✓
3	1	Front Bonnet Lock <i>Damaged.</i>		\$210.20 ✓
4	1	Front Bonnet Lock Outer Garnish <i>New</i>		\$27.35 ✓
5	1	Front Bonnet Insulator <i>3 pr</i>		\$236.10 ✓
6	12	Front Bonnet Insulator Clip <i>3 pr</i>	\$6.50	\$78.00 ✓
7	2	Front Bonnet Shock Absorber <i>New</i>	\$125.00	\$250.00 ✓
8	1	Front Bonnet Weatherstrip <i>New</i>		\$95.00 ✓
9	2	Front Bonnet Lock Hinge <i>New</i>	\$89.20	\$178.40 ✓
10	2	Front Headlamp <i>LH smashed.</i>	\$13081	<del>\$26162</del> 13081 ✓
11	2	Front Headlamp ECU <i>Damaged</i>	\$1,601.30	<del>\$3,202.60</del> 1114 ✓
12	1	Front L/H Head Lamp Fan Motor <i>Missing</i>		\$650.00 385 ✓
13	3	Front Headlamp Lower Bracket <i>Smashed.</i>	\$43.00	\$129.00 ✓
14	1	Front Support Panel <i>Distorted.</i>		\$1131 ✓
15	1	Front Support Panel Top Garnish <i>3 pr</i>		\$174.85 ✓
16	8	Front Support Panel Top Garnish Clip <i>3 pr</i>	\$6.50	\$52.00 ✓
17	1	Front Support Panel Side Cover <i>tor</i>		\$25.90 ✓
18	2	Front Support Panel Front Air Guide <i>LH torn</i>	<del>(\$38.00)</del>	\$76.00 38 ✓
19	1	Front Support Panel L/H Lock Bracket <i>Damaged.</i>		\$93.00 ✓
20	1	Front Radiator <i>3 Best</i>		\$1335 ✓
21	1	Front Radiator Inner		\$1134 ✓
22	1	Front Air Con Condensor <i>Best.</i>		\$1,084.55 ✓
23	1	Front Air-Con Condenser Fan Motor Assy <i>New</i>		\$2,537.75 ✓
24	1	Front Air-Con Condenser Section Pipe <i>3 Best</i>		\$308.50 ✓
25	1	Front Air-Con Condenser Discharge Pipe		\$420.30 ✓
26	1	Front Air-Con Condenser Section Hose <i>3 Best</i>		\$571.70 ✓
27	1	Front Air-Con Condenser Discharge Hose		\$350.30 ✓
28	1	Front Intercooler <i>Distorted</i>		\$1,898.35 ✓

807.

29	1	Front Intercooler Bracket	Bent		\$235.00	✓
30	2	Front Intercooler Piping	Not nec.	\$95.00	\$190.00	+
31	2	Front Intercooler Side Garnish	Distorted	\$45.00	\$90.00	✓
32	1	Front Secondary Air Pump	cracked.		\$1,272.25	✓
33	2	Front Horn	LH Paged	\$85.00	\$170.00	85. ✓
34	1	Front Engine Coolant	new		\$406.05	+
35	1	Front Engine Lower Cover	new		\$1,003.25	+
36	1	Front Grille	cracked		\$2,691.35	✓
37	1	Front Grille Parking Sensor Cover	Damaged		\$45.00	✓
38	1	Front Bumper	Distorted.		\$2649	✓
39	10	Front Bumper Clip	new	\$6.50	\$65.00	✓
40	1	Front L/H Bumper Side Retainer	Distorted		\$47.00	✓
41	1	Front L/H Bumper Air Duct	Distorted.		\$109.00	✓
42	1	Front Bumper Inner Center Garnish	Distorted.		\$80.15	✓
43	1	Front Bumper Reinforcement	Bent		\$1157	✓
44	1	Front Bumper Reinforcement Foam	cracked		\$104.95	✓
45	1	Front L/H Bumper Reinforcement Bracket	new		\$27.35	+
46	1	Front Bumper Towing Cover	new		\$64.00	+
47	1	Front Bumper Nozzle	Distorted		\$202.65	✓
48	1	Front Bumper Nozzle Motor	Smoked		\$365.00	✓
49	1	Front Bumper Nozzle Rubber Hose	new		\$185.00	+
50	4	Front Bumper Parking Sensor	2 pieces damaged	\$204.75	\$819.00	409-50 ✓
51	1	Front L/H Bumper Fog Lamp Cover	missing		\$382.00	✓
52	1	Front Bumper Center Moulding	cracked		\$516.10	✓
53	1	Front Bumper Undercover	torn		\$262	✓
54	1	Front L/H Fender	Distorted		\$1,370.40	✓
55	1	Front L/H Fender Inner Panel	Repair		\$580.00	+
56	1	Front L/H Fender Cowling	torn		\$218.65	✓
57	1	Front L/H Fender Cowling Clip	new		\$117.55	50 ✓
58	1	Front L/H Fender Side Bar	Bent		\$851	✓
59	1	Front L/H Fender Side Bracket	Bent		\$181.05	✓
60	1	Front L/H Fender Side Frame	Bent		\$613	✓
61	1	Front Dashboard	torn		\$8497	✓
62	2	Front Visor	cracked	\$520.85	\$1,041.70	✓
63	2	Roof Side Garnish	lit	\$440.35	\$880.70	✓
64	1	Front Air Bag R/H	Activated.		\$4875	✓
65	1	Front Air Bag L/H			\$4417	✓
66	1	Front Air Bag Sensor	Activated		\$251.05	✓
67	1	Front Air Bag ECU			\$2,171.75	✓
68	1	Roof Air Bag R/H	Activated		\$1923	✓
69	1	Roof Air Bag L/H			\$1923	✓
70	1	Roof Panel Trimboard	cracked		\$4929	✓
71	1	L/H Roof Panel Cabin Lamp	Damaged.		\$135.65	✓

72	2	Front Seatbelt	Aclinted	\$2032	\$4064	✓
73	1	Front Seatbelt Adjuster Motor Assy	N/A		\$387.00	+
74	2	Rear Seatbelt	Aclinted	\$643	\$1286	✓
75	2	Rear Seatbelt Stopper Clip	New	\$38.00	\$76.00	✓
76	1	Front L/H Tyre	A/A		\$800.00	+
1759	77	1	Front L/H Rim	at.	\$1759	✓
78	1	Front L/H Shock Absorber	N/A		\$4,398.80	+
79	1	Front L/H Knuckle Arm	Dund		\$1,169.50	✓
80	1	Front L/H Knuckle Arm Bearing	New		\$625.95	✓
81	1	Front L/H Stabilizer Bar	Best.		\$568.45	✓
82	1	Front L/H Trailing Arm	Best		\$1,022.50	✓
83	1	Front L/H Upper Arm	Best		\$330.75	✓
84	1	Front L/H Lower Arm	Best.		\$540.00	✓
85	1	Front L/H Tie Rod End	New		\$438.00	+
86	1	Front L/H Driveshaft	X/A New		\$2,922.95	+
87	1	Front Steering Rack	Z/A		\$6,890.75	+
88	1	Front Crossmember	J/A		\$3,728.40	+

75 1144  
681727  
855429.85  
76886.86

Subtotal :- \$115,538.79

Labour charges

To remove & refit air bags & install airbag unit	<del>\$3,000.00</del> 1000
To remove & refit air-con condenser, radiator, fan motor, manifold, intercooler, air-con compressor & top up gas	<del>\$650.00</del> 350
To remove & refit air con pipes & hose	<del>\$550.00</del> 150
To remove & refit front dashboard	<del>\$1,000.00</del> 380
To remove & refit cushion & trim board	<del>\$800.00</del> 400
To remove & refit reverse sensor	<del>\$200.00</del> 60
To reset computer	<del>\$800.00</del> 200
To remove & refit front L/H undercarriage	<del>\$1,000.00</del> 380
To check wheel alignment	<del>\$150.00</del> 80

To check wiring

~~\$200.00~~ 100

Towing fee

~~\$150.00~~ 120

Tuff kote

6420

~~\$150.00~~ 100

Panel Beating

~~\$3,500.00~~ 1800

Spray painting

~~\$3,000.00~~ 1300

Subtotal :- \$15,150.00

Total:- \$130,688.79

total: 8330686.00

4/s: 66.6/46

21 Days.

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: