

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

Email: erofia@singnet.com.sg

AIG

Name : Saravanan A/L Ramachandran

Accident Date : 17-Mar-21

Vehicle No : JSR1438

Vehicle Model : Honda FS150FJ

Estimated Repair Costs

Qty	Description List Items	Amount S(\$)
1	Rear signals (1 set) <i>SNA</i>	\$ 160.00
1	Rear swing arm <i>SW</i>	\$ 300.00
1	Rear rim <i>R</i>	\$ 420.00
1	Rear rim shaft <i>17</i>	\$ 60.00
1	Rear rim bearing <i>17</i>	\$ 90.00
1	Rear rim brake disc <i>17</i>	\$ 175.00
1	Rear taillamp <i>CNE</i>	\$ 250.00
1	Rear fender <i>BNO</i>	\$ 180.00
1	Exhaust protector front <i>17</i>	\$ 105.00
1	Exhaust end cap cover <i>CUT</i>	\$ 85.00
1	Rear number plate lamp <i>SCR</i>	\$ 115.00
		\$ 1,940.00
	Less 10%	\$ 194.00
		\$ 1,746.00
1	Special Net Items	
	Rear number plate <i>Benf</i>	\$ 15.00
		\$ 15.00
S/No.	Labour	
1	To provide towing service	\$ 50.00
2	To provide labour	\$ 380.00
		\$ 430.00
	Grand Total	\$ 2,191.00

Not Allowed
4/6 # 750
2 hrs.
23/3/21
Why not of survey

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Singapore Dollars: Two Thousand One Hundred Ninety-One only

EROFIA MOTOR TRADING PTE LTD

790
951