



BLACK EAGLE AUTO PTE LTD

SYNERGY@KB
25 KAKI BUKIT ROAD 4
#05-80
SINGAPORE 417800
Tel: 6951 3770
Blackeagleauto@gmail.com

Date: 19/03/2021
To: INDIA INT'L INS PTE LTD

*not Authorized
LKLK
23-3-21 22/3/21
H/S
6 days
take hold After repair
cost plus 10%*

Motor Claims Department

Dear Sir/Mdm,

NOTIFICATION OF ACCIDENT

Please be informed that an accident involving my/our vehicle(s) no. SGK9999T had taken place at/along Lor 18 Geylang on date 18/03/21 at time 15:00hrs.

Kindly let us know within 2 working days from the date of this notice if you wish to carry out or waive a pre-repair inspection.

If we do not hear from you within 2 working days, we shall proceed to repair vehicle without further notice and our client shall claim for the additional loss of use arising from the giving of this notification to you.

Please call 6951 3770 / 9635 4538 to arrange.

Yours sincerely,

PRI

Date / Time	23-3-21 / 22/3/21
Company Name	LKLK
Surveyor	not by
Contact No.	90096608
Signature	02563561

DISMANTLED PARTS

Date / Time	
Surveyor	

AFTER REPAIR

Date / Time	
Surveyor	

VEHICLE NO SGK 9999T MERCEDES BENZ C180

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYOR'S ADJUSTMENT
<u>PARTS (LIST ITEMS)</u>				
1	Front Bumper		2300.00	Dis —
2	Front Bumper side chrome @180		360.00	nei —
1	Front Bumper centre grille		340.00	70% —
1	Front Bumper sponge		113.00	70% —
1	Front Bumper reinforcement		560.00	50% —
1	Front Bumper under cover		356.00	cr —
2	Front Bumper bracket @105		210.00	0/5 cr lpc
1	Front bumper tow cover		72.00	c/w bumper X
1	RHS & LHS Front bumper fog lamp @492.50		985.00	0/5 cr lpc
1	Front centre stiffening frame		218.00	?
1	A/C condensor		1100.00	?
1	Radiator		950.00	?
1	Radiator fan assy		554.00	?
1	Radiator fan cowling		245.00	?
1	Radiator top cover		112.00	cr —
2	Front centre side duct @120		240.00	0/5 70% lpc
1	A/c condensor pipe outlet		240.00	?
1	A/c condensor pipe inlet		220.00	?
1	Wiper washer tank		398.00	17X
1	Wiper washer tank motor		190.00	17X
1	Front RHS member bracket		430.00	?
1	Front small pulley		280.00	17X
1	Front small pulley belt		120.00	?
1	Front engine air hose		540.00	17X
1	Front engine air inlet hose		280.00	17X
1	Front bonnet		2120.00	30% —
2	Front bonnet hinges @\$255		510.00	12X
1	Front bonnet badge (grommet)		98.00	nei —
1	Front bonnet heat insulator		210.00	17X
2	Front bonnet top lock catch@45		90.00	50% X
1	Front RHS bonnet lock		242.00	50% X
1	Front radiator grille		680.00	cr —
1	Front grille Mercedes star emblem		122.00	cr —
1	Front support panel		580.00	30% —
2	Front horn @\$185		370.00	17X
2	RHS & LHS Headlamp (halogen) @1100.00		2200.00	0/5 cr lpc n/s?
2	RHS & LHS Headlamp lower bracket@237.50		475.00	NSX
1	RHS Front Fender		1250.00	30% cr —
1	RHS Front Fender inner shield		280.00	17X
			20640.00	
		less 10%	2064.00	10%
			18576.00	

<u>SPECIAL NETT ITEMS</u>			
1set	Front bumper clips	40.00	net 30
1set	RHS Front fender inner shield clips	40.00	17 X
1set	Front bonnet heat insulator clips	40.00	17 X
2	Front sensor @255	510.00	NI X
1	Front license plate moulding	50.00	} sub 40
1	Front license plate	35.00	
1	Radiator coolant	60.00	net 30
TOTAL PARTS		19351.00	

VEHICLE NO SGK 9999T MERCEDES BENZ C180

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	SURVEYOR'S ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	1200.00	600
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	1000.00	700
3	To remove and check/refix wiring and focus headlamp beam	150.00	30
4	To clear fault code with diagnostic computer and reset to specification	300.00	NNX
5	To remove and replace radiator, pressure test and refill coolant	150.00	NNX
6	To perform anti-rust treatment on affected areas	150.00	NNX
	Labour Total :	2950.00	
TOTAL (PARTS & LABOUR):		22301.00	

NOTE: The parts listed in this preliminary estimate will be checked for damage after the vehicle is disassembled (dismantle). Additional damaged parts (if any) will be submitted as supplementary p:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To resurvey damaged part(s) during resurvey
- To provide confirmation
- To provide confirmation on "justice" basis
- No illegal modification allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: