

VEHICLE NO SGK 9999T MERCEDES BENZ C180

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYOR'S ADJUSTMENT
	PARTS (LIST ITEMS)			
1	Front Bumper	900	2300.00	Dis ✓
2	Front Bumper side chrome @180	70x2=140	360.00	net ✓
1	Front Bumper centre grille	75	340.00	Torn ✓
1	Front Bumper sponge	80	113.00	70.9 ✓
1	Front Bumper reinforcement	200	560.00	scr ✓
1	Front Bumper under cover	180	356.00	cr ✓
2	Front Bumper bracket @105	55x2=110	210.00	o/s cr 6c
1	Front bumper tow cover	60	72.00	c/w huan X
2	RHS & LHS Front bumper fog lamp @492.50	280x2=560	985.00	o/s cr 1pc
1	Front centre stiffening frame	80	218.00	cr ✓
1	A/C condensor	850	1100.00	Beat/pun ✓
1	Radiator	500	950.00	Pun/cr ✓
1	Radiator fan assy	710	554.00	cr/scr ✓
1	Radiator fan cowling	620	245.00	X
1	Radiator top cover	85	112.00	cr ✓
2	Front centre side duct @120	40 x2=80	240.00	o/s Torn 1pc
1	A/c condensor pipe outlet	260	240.00	net
1	A/c condensor pipe inlet	260	220.00	net
1	Wiper washer tank	110	398.00	17x
1	Wiper washer tank motor	55	190.00	17x
1	Front RHS member bracket	180	430.00	net
1	Front small pulley	76	280.00	17x
1	Front small pulley belt	115	120.00	net
1	Front engine air hose	65	540.00	17x
1	Front engine air inlet hose	60	280.00	17x
1	Front bonnet	1200	2120.00	34c ✓
2	Front bonnet hinges @\$255	70x2=140	510.00	2x
1	Front bonnet badge (grommet)	50	98.00	net ✓
1	Front bonnet heat insulator	200	210.00	17x
2	Front bonnet top lock catch@45	25x2=50	90.00	scr X
1	Front RHS bonnet lock	45	242.00	scr X
1	Front radiator grille	410	680.00	cr ✓
1	Front grille Mercedes star emblem	25	122.00	cr ✓
1	Front support panel	90	580.00	scr ✓
2	Front horn @\$185	110	370.00	17x
2	RHS & LHS Headlamp (halogen) @1100.00	400x2=800	2200.00	o/s cr 1pc
2	RHS & LHS Headlamp lower bracket@237.50	50	475.00	NSX
1	RHS Front Fender	510	1250.00	34c/cr ✓
1	RHS Front Fender inner shield	85	280.00	Torn ✓
			20640.00	
		less 10%	2064.00	10%
			18576.00	
				6945

NSX

<u>SPECIAL NETT ITEMS</u>			
1set	Front bumper clips	40.00	net 30
1set	RHS Front fender inner shield clips	40.00	17 X
1set	Front bonnet heat insulator clips	40.00	17 X
2	Front sensor @255	510.00	NI X
1	Front license plate moulding	50.00	> net 40
1	Front license plate	35.00	
1	Radiator coolant	60.00	net 30
TOTAL PARTS		19351.00	

VEHICLE NO SGK 9999T MERCEDES BENZ C180

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	SURVEYOR'S ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	1200.00	600
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	1000.00	700
3	To remove and check/refix wiring and focus headlamp beam	150.00	30
4	To clear fault code with diagnostic computer and reset to specification	300.00	NNX
5	To remove and replace radiator, pressure test and refill coolant	150.00	NNX
6	To perform anti-rust treatment on affected areas	150.00	NIX
	Labour Total :	2950.00	
TOTAL (PARTS & LABOUR):		22301.00	

NOTE: The parts listed in this preliminary estimate will be checked for damage after the vehicle is disassembled (dismantle). Additional damaged parts (if any) will be submitted as supplementary p:

7-8335
 102

 7,9168.50
 S/W-100
 L-1330

 10598.50
 202

 8478.50

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To resurvey damaged part(s) during resurvey
 • To resurvey damaged part(s) during resurvey
 • To resurvey damaged part(s) during resurvey
 • No illegal modification allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
 Acknowledged by Repairer
 Signature:
 Date:

VEHICLE NO SGK9999T MERCEDES BENZ C180
 (SUPPLYMENTARY)

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYOR'S ADJUSTMENT
1	Intercooler	\$750	1800.00	PA ✓
1	Intercooler hose 1	\$160	160.00	Tom ✓
1	Intercooler hose2	\$200	220.00	Tom ✓
1	Front bumper centre grille inner frame	\$120	240.00	CA ✓
1	RHS headlamp housing	\$160	280.00	Ben ✓
		TOTAL PARTS	2700.00	