



1 Kaki Bukit Ave 6, # 02-22/21/20 @ Autobay Blk D Singapore 417883
Company & GST Registration No : 201828067M

VEHICLE INSPECTION ESTIMATE

M/S : India international Insurance Pte Ltd
(MOTOR CLAIM DEPARTMENT)

Email motorclaim@iii.com.sg

Carilia.

Parts - (%)	
SN	
Labour	
Lump sum	
ERV	

Vehicle No: SMV2124T Date: 24.03.2021
Vehicle Model: HONDA VEZEL Reg. Date: 26.09.2016
Chassis No: RU11113042 D.O.A: 15.03.2021

S/No.	Item Description	Qty	Price	Total Cost	Surveyor Use
1	Bonnet	1	\$ 892.30	\$ 892.30	+
2	Bonnet Hinges	2	\$ 68.50	\$ 137.00	+
3	Bonnet Insulator	1	\$ 122.30	\$ 122.30	+
4	Bonnet Side Rubber Moulding - side, long	2	\$ 57.50	\$ 115.00	+
5	Bonnet Lock	1	\$ 98.50	\$ 98.50	+
6	Bonnet Stoppers	4	\$ 25.00	\$ 100.00	+
7	Bonnet Emblems	3	\$ 28.00	\$ 84.00	+
8	Headlamp Assy LH	1	\$ 1,810.50	\$ 1,810.50	✓
9	Headlamp Bracket LH	1	\$ 70.00	\$ 70.00	+
10	Headlamp Side Top Garnish	2	\$ 65.10	\$ 130.20	+
11	Front Bumper	1	\$ 592.60	\$ 592.60	✓
12	Bumper Side Retainer	1	\$ 68.30	\$ 68.30	38
13	Front Bumper Lower	1	\$ 265.60	\$ 265.60	✓
14	Bumper Radiator Grille Base	1	\$ 341.40	\$ 341.40	+
15	Bumper Radiator Grille - Outer	1	\$ 283.40	\$ 283.40	+
16	Bumper Grille Emblem H Logo	1	\$ 43.40	\$ 43.40	+
17	Bumper Chrome Garnish	2	\$ 86.90	\$ 173.80	+
18	Bumper Grille Bracket	1	\$ 107.50	\$ 107.50	+
19	Bumper Radiator Grille Lower	1	\$ 68.10	\$ 68.10	+
20	Bumper Top Garnish	1	\$ 125.00	\$ 125.00	+

C/F \$ 5,628.90



1 Kaki Bukit Ave 6, # 02-22/21/20 @ Autobay Blk D Singapore 417883
Company & GST Registration No : 201828067M

VEHICLE INSPECTION ESTIMATE

S/No.	Item Description	Qty	B/F Price	\$ 5,628.90 Total Cost	Surveyor Use
21	Fog Lamp LH <i>for</i>	1	\$ 427.00	\$ 427.00	<i>+</i>
22	Fog Lamp Bracket LH <i>for</i>	1	\$ 80.00	\$ 80.00	<i>+</i>
23	Fog Lamp cover LH <i>cut</i> NN	1	\$ 75.00	\$ 75.00	<i>X</i>
24	Engine Undercover <i>new</i>	1	\$ 146.80	\$ 146.80	<i>+</i>
25	Front Reinforcement <i>Dented</i>	1	\$ 421.00	\$ 421.00	<i>+</i> 321
26	Front Reinforcement Garnish <i>new</i>	2	\$ 44.20	\$ 88.40	<i>+</i>
27	Support panel <i>new</i>	1	\$ 576.20	\$ 576.20	<i>+</i>
28	Support panel Air Guide <i>new</i>	2	\$ 56.60	\$ 113.20	<i>+</i>
29	Air Intake Air Duct - Outer pc <i>new</i>	1	\$ 77.50	\$ 77.50	<i>+</i>
30	Horn <i>new</i>	1	\$ 58.00	\$ 58.00	<i>+</i>
31	AC Condenser <i>for new</i>	1	\$ 568.10	\$ 568.10	<i>+</i>
32	Radiator Assy <i>for new</i>	1	\$ 1,250.60	\$ 1,250.60	<i>+</i>
33	Front Fender LH <i>Repair</i>	1	\$ 630.00	\$ 630.00	<i>+</i>
34	Front Fender Protector LH <i>cut</i>	1	\$ 213.00	\$ 213.00	<i>+</i>
35	Front Fender Cowling LH <i>new</i>	1	\$ 180.00	\$ 180.00	<i>+</i>

3240.70
2592.56.

Total For List Items: \$ 10,533.70
Less Spare Parts Discount (20%): \$ 2,106.74
Total: \$ 8,426.96

SPECIAL NETT ITEMS

S/No.	Item Description	Qty	Price	Total Cost	Surveyor Use
1	Front Bumper Clips 1set <i>new</i>	1	\$ 30.00	\$ 30.00	<i>+</i>
2	Front Bumper Top Garnish Clips 1set <i>new</i>	1	\$ 30.00	\$ 30.00	<i>+</i>
3	Front Reinforcement Garnish Clips 1set <i>new</i>	1	\$ 30.00	\$ 30.00	<i>+</i>
4	Engine Undercover Clips 1set <i>new</i>	1	\$ 30.00	\$ 30.00	<i>+</i>
5	Front Fender Clips 1set <i>for new</i>	1	\$ 30.00	\$ 30.00	<i>+</i>
6	Front Num Plate W Casing 1set <i>for new</i>	1	\$ 70.00	\$ 70.00	<i>+</i>

Total For S/N Items: \$ 220.00

30

C/F \$ 8,646.96



B/F \$ 8,646.96

LABOUR

S/No.	Item Description	Qty	Price	Total Cost	Surveyor Use
1	To straighten/realign accident affected portion	1	\$ 1,000.00	\$ 1,000.00	300
2	To respray accident affected portion.	1	\$ 1,200.00	\$ 1,200.00	400.
3	To dismantle, replace and/or repair air con condenser & refill air con gas	1	\$ 150.00	\$ 150.00	x
4	To dismantle, replace and/or repair radiator and pressure test	1	\$ 150.00	\$ 150.00	x
5	To check wiring/wire connector and rewire/repair	1	\$ 100.00	\$ 100.00	x
6	To check and realign headlamp	1	\$ 80.00	\$ 80.00	30.

Total For Labour: \$ 2,680.00

730

Adrian Lj
L/s 25/03/21
03 Days

total: 3352.56

L/s 2.61c.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: