



Exceptional Journeys

Surveyor : Steve LKK
Ins Company : CHINA TAIPING
DOA : 20/3/2021
CSE : EDWIN
Date of Survey : 17/5/2021

VEHICLE NO : SCV9848K
MODEL : MIT/ OUTLANDER 2.0 2WD CVT
WIP : 64289

Material	:	\$	3,727.00
Labour	:	\$	2,740.00
Sub-Total	:	\$	6,467.00
Less Excess	:	\$	-
Total	:	\$	6,467.00
GST 7%	:	\$	452.69
Grand Total	:	\$	6,919.69
Finalise By/Date	:		Patrick 7/6/2021

Email :

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 4 WORKING DAYS + 0 Days (0) Weekends
+ 0 Days (0) Public Holiday
+ 1 Survey - 17/05/2021 Mon
TOTAL DAYS REPAIR TOOK = 5

☐ TP Claim _____

☐ Claim GIA / LTA fee _____

☐ Claim Loss ☐ Use ☐ Rental

☐ Claim Medical Fee / Others _____

☐ Third Party Report _____

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Wong Ngee Hua (yuan Yihua)	Cust No/Name	/Wong Ngee Hua (Yuan Yihua)
Blk 661C Jurong West St 64	Reg No/Reg Date	SCV9848K / 02/05/2018
#14-434	Date In/Mileage	17/05/2021/ 47035
Singapore 643661	Chassis/Package	GF7W0401601
Contact No Mobile: 98480232	Engine No	4J11YA4855
17/05/2021	Make/Model	MIT/OUTLANDER 2.0 2WD CVT SPORTS (992)
	Colour/Trim	U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00040	Cash	07/06/2021/ 10:25	TLE	289 / Patrick Lee	64289

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW FRT BUMPER				/ 720.00
A 54900099 CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM				/ 30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				/ 280.00
M SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS				/ 40.00
M SUNDRY Sundries				/ 20.00
E PNT98000 SPRAY PAINT WORK ON FRT BUMPER, FRT BUMPER BODY KIT & RH FENDER				/ 1650.00
X HEADLAMP ASSY,RH	1.00	2135.00	00.00	/ 2135.00
X MOULDING,FR BUMPER,RH	1.00	116.00	00.00	/ 116.00
X MOULDING,FR WHEEL ARCH,RH	1.00	199.00	00.00	/ 199.00
X GARNISH,FR BUMPER,RH	1.00	75.00	00.00	/ 75.00
X FACE,FR BUMPER	1.00	1172.00	00.00	/ 1172.00
X RIVET,FR BUMPER — SUPP	6.00	5.00	00.00	30.00
Z TEXT TP CLAIM-CHINA TAIPING DOA:20/03/2021 SURV: STEVE LKK 17/05/2021 04 DAYS				
<i>Guarantee Your Warranty, Maintain with Cycle & Carriage!</i>				

Parts	3,727.00	Nett	6,467.00
Labour	2,680.00	7% GST on	452.69
Standard Menu	0.00		
Specialist Job	0.00	Total Payable	6,919.69
Diagnostics Job	0.00		
Sundry/Others	60.00		
Total(w/o GST)	6,467.00		

This is not an official tax invoice.
 This is a computer generated document, no signature is required.

SUPPLEMENTARY

INSURANCE CO : CHINA TAIPING INSURANCE (S) PTE LTD

REGISTRATION NO : SCV9848K

S/N	Description	Qty	Unit Price	Disc%	Amount
<u>PARTS</u>					
1	RIVET, FR BUMPER <i>nec</i>	6.00	5.00	0.00	30.00 ✓
Total					30.00
7 % GST					2.10
Grand Total					32.10

Thank You.

Yours faithfully

CYCLE & CARRIAGE FRANCE PTE LTD

Patrick Lee

WIP: 64289

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	RIVET FR. BU (x6) (x6) (x6)	? / SUPP	6/10		MUO01657
2		? / SUPP			
3		? / SUPP			
4		? / SUPP			
5		? / SUPP			
6		? / SUPP			
7		? / SUPP			
8		? / SUPP			
9		? / SUPP			
10		? / SUPP			
11		? / SUPP			
12		? / SUPP			
13		? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

	DATE	TAKEN BY
PHOTO BEFORE PAINT	19/5	tdh
PHOTO AFTER PAINT		
PHOTO OF MOUNT TO CELLLETE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBAORD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: MIT OUTLANDER 2.0

SURVEYOR: STEVE LKK