



CYCLE & CARRIAGE

AIG - OD (REVERT)
SURVEY: 22/03/21
LHK - STEVE

VEHICLE NO : SMY 3173D

MODEL : MIT/ATRAGE 1.2 CVT

WIP : 64300

Material	:	\$	<u>3,743.71</u>
Labour	:	\$	<u>8,485.00</u>
Sub-Total	:	\$	<u>12,228.71</u>
Less 2% Disc	:	\$	<u>—</u>
Less Excess	:	\$	<u>—</u>
Total	:	\$	<u>12,228.71</u>
GST 7%	:	\$	<u>856.01</u>
Grand Total	:	\$	<u>13,084.72</u>
Finalise By/Date : <u>LARRY on 29/04/21</u>			

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 17 WORKING DAYS + 6 days (3 weekends)

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info		
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 22/03/2021	Cust No/Name	KCV18871/SUBRAMANIAN SENTHIL KUMAR	
	Reg No/Reg Date	SMY3173D / 26/02/2021	
	Date In/Mileage	22/03/2021/ 559	
	Chassis/Package	MMBSTA13AMH002993	
	Engine No	3A92UJT9423	
	Make/Model	MIT/21MY ATTRAGE 1.2 CVT (E31)	
	Colour/Trim	U01 TITANIUM GREY M/ BK BLACK	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	28/04/2021/ 17:14	BLK	884 / Lauro Songcuan	64300

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE REAR BUMPER, BOOT, END PANEL, LH TAIL LAMP PANEL, REAR LH FENDER & AFFECTED AREA, REPAIR ON REAR RH FENDER				2700.00 ✓
E PNT98000 SPRAY PAINT ON REAR BUMPER, REAR BOOT, END PANEL, REAR LH TAIL LAMP PANEL & BOTH REAR FENDER				1925.00 ✓
E PNT88000 REMOVE & INSTALL REAR PARKING ASSIST				80.00 ✓
E PNT88000 REMOVE & INSTALL REAR WINDSCREEN FOR FACILITATE REPAIR				240.00 ✓
M SUNDRY APPLY REAR WINDSCREEN GLASS SEALANT				80.00 ✓
E PNT88000 REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR				120.00 ✓
E PNT88000 REMOVE & INSTALL REAR SEAT FOR FACILITATE REPAIR				120.00 ✓
M SUNDRY APPLY BODY SEALANT ON AFFECTED AREAS				80.00 ✓
M SUNDRY PERFORM RUST PREVENTION ON AFFECTED AREAS				40.00 ✓
A 13900099 REMOVE & INSTALL REAR FUEL TANK FOR FACILITATE REPAIR				450.00 ✓
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				30.00 ✓
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00 ✓
M SUNDRY SUPPLY C&C EMBLEM				50.00 ✓
E PNT88000 TRANSFER REAR BOOT COMPARTMENT TO NEW PANEL				120.00 ✓
M SUNDRY SUNDRIES				30.00 ✓

This is not an official tax invoice.
 This is a computer generated document, no signature is required.

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info		
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 22/03/2021	Cust No/Name	KCV18871/SUBRAMANIAN SENTHIL KUMAR	
	Reg No/Reg Date	SMY3173D / 26/02/2021	
	Date In/Mileage	22/03/2021/ 559	
	Chassis/Package	MMBSTA13AMH002993	
	Engine No	3A92UJT9423	
	Make/Model	MIT/21MY ATTRAGE 1.2 CVT (E31)	
	Colour/Trim	U01 TITANIUM GREY M/ BK BLACK	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No				
KAX00008	Credit	28/04/2021/ 17:14	BLK	884 / Lauro Songcuan	64300				
Description of Goods / Services						Qty	Unit Price	Disc%	Amount
E PNT88000 REMOVE & INSTALL REAR REVERSE CAMERA → <i>supp.</i>									80.00 X
E PNT88000 REPLACE TAILLAMP PANEL LH, EXTENSION QTR PANEL LH, → <i>supp.</i> REPAIR REAR FLOOR PANEL & REAR LH SIDE MEMBER									1125.00 X
E PNT98000 SPRAY PAINT TAILLAMP PANEL LH, EXTENSION QTR PANEL LH, → <i>supp.</i> REAR FLOOR PANEL & REAR LH SIDE MEMBER									875.00 X
S SPECIALISTJOB SUPPLY REAR REVERSE SENSOR									220.00 ✓
X LAMP ASSY, COMB, RR LH						1.00	509.00	23.00	391.93 ✓
X FACE, RR BUMPER						1.00	654.00	23.00	503.58 ✓
X PANEL, QTR, OTR LH						1.00	808.00	23.00	622.16 ✓
X PANEL, RR COMB LAMP HSG, LH						1.00	60.00	23.00	46.20 ✓
X PANEL, RR END						1.00	427.00	23.00	328.79 ✓
X STOPPER, WINDSHIELD GLASS						2.00	3.00	23.00	4.62 ✓
X SPACER, RR WINDOW						3.00	9.00	23.00	20.79 ✓
X WEATHERSTRIP, TRUNK LID						1.00	157.00	23.00	120.89 ✓
X PANEL, TRUNK LID						1.00	795.00	23.00	612.15 ✓
X HINGE, TRUNK LID, LH ?						1.00	203.00	23.00	156.31 ?
X SHIELD, RR WHEELHOUSE, LH						1.00	40.00	23.00	30.80 ✓
X MARK, THREE-DIA						1.00	70.00	23.00	53.90 ✓
X MARK, ATTRAGE						1.00	21.00	23.00	16.17 ✓
X TRIM, RR END						1.00	66.00	23.00	50.82 ✓
X BOARD, TRUNK ROOM FLOOR						1.00	195.00	23.00	150.15 ✓
X BRACKET, RR BUMPER, LH ?						1.00	28.00	23.00	21.56 ?
X CLIP, FR BUMPER → <i>supp.</i>						10.00	4.00	23.00	30.80 X
X EXTN, QTR PANEL, UPR OTR LH ?						1.00	118.00	23.00	90.86 ?
X BUZZER, KEYLESS OPERATIO, RR						1.00	91.00	23.00	70.07 X
X COVER, RR VENTILATOR → <i>supp.</i>						1.00	35.00	23.00	26.95 X
X MUD GUARD, RR LH ?						1.00	35.00	23.00	26.95 ?
X GROMMET, TAIL LAMP → <i>supp.</i>						2.00	3.00	23.00	4.62 X
X GARNISH, RR END PANEL X						1.00	336.00	23.00	258.72 ?

This is not an official tax invoice.
 This is a computer generated document, no signature is required.

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info		
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 22/03/2021	Cust No/Name	KCV18871/SUBRAMANIAN SENTHIL	KUMAR
	Reg No/Reg Date	SMY3173D	/ 26/02/2021
	Date In/Mileage	22/03/2021/	559
	Chassis/Package	MMBSTA13AMH002993	
	Engine No	3A92UJT9423	
	Make/Model	MIT/21MY ATTRAGE 1.2 CVT (E31)	
	Colour/Trim	U01 TITANIUM GREY M/ BK	BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	28/04/2021/ 17:14	BLK	884 / Lauro Songcuan	64300

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X ANT,KEYLESS OPERATION,RR → <i>supp.</i>	1.00	96.00	23.00	73.92 X
X EMBLEM MIVEC TECHNOLOGY → <i>quoted as summary</i>	1.00	30.00	00.00	30.00 ✓
Z TEXT AIG OD CLAIM - REVERT DOA: 21.03.2021 SURVEY: STEVE (LKK) 17 DAYS				
Pro Forma				
<i>Guarantee Your Warranty, Maintain with Cycle & Carriage!</i>				

Parts	3,743.71		Nett	12,228.71
Labour	7,985.00	7% GST on	12228.71	856.01
Standard Menu	0.00			
Specialist Job	220.00		Total Payable	13,084.72
Diagnostics Job	0.00			
Sundry/Others	280.00			
Total(w/o GST)	12,228.71			

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

INSURANCE CO.: AIG

Supplementary For Registration No.: SMY 3173 D

<u>Materials</u>		<u>Cost \$</u>	
1	Clip, FR Bumper (10 pcs)	40.00	✓ nec
2	Buzzer, Ketless Operation, RR	91.00	✓ BR
3	Cover, RR Ventilator	35.00	✓ BR
4	Grommet, Tail Lamp (2 pcs)	6.00	✓ nec
5	Ant, Keyless Operation, RR	96.00	✓ BR
		268.00	
23% Discount		61.64	
		206.36	
<u>Labour</u>			
1	Remove & Install Reverse Camera	80.00	✓
2	Replace Tail Lamp Panel LH, Extension Qtr Panel LH, Repair Rear Floor Panel & Rear LH Side Member	1,125.00	✓
3	Spray Paint Tail Lamp Panel LH, Extension Qtr Panel LH, Rear Floor Panel & Rear LH Side Member	875.00	✓
		2,080.00	
Labour & Materials		2,286.36	
7% GST		160.05	
Total		2,446.41	

Thank You.

Yours faithfully

CYCLE & CARRIAGE AUTOMOTIVE PTE LTD

Larry Songcuan
Customer Service
Cycle & Carriage
Pandan Gardens
Tel. # 6568 4658

CAR NO: SMY 3173DWIP: 64300

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	Bracket Rear Bumper LH	? / SUPP		✓ BR	7
2	Extension OTR panel, Upr. OTR LH	? / SUPP		✓ BT	
3	Hinge Trunk lid LH	? / SUPP		✓ BT	
4	Mud Guard RR LH "Missing"	? / SUPP		✓ MS (Bumper trim body)	
5	Garnish Rear End Panel.	? / SUPP		✓ BR (Bottle cap)	
6	Buzzer	? / SUPP		✓ BR	
7	Smart Key Sensor	? / SUPP		✓ BR	
8	Air Duct Cover	? / SUPP		✓ BR	
9	Grommet Tailamp X 2	? / SUPP		✓ MC	
10	Clip Rear Bumper X 10	? / SUPP		✓ MC	
11		? / SUPP			
12	Repair floor Panel	✓ \$450		✓	
13	Repair Rear LH Sidemember	✓ \$450		✓	
14	Replace tailamp panel LH	✓ \$450		✓	
15	Replace Extension Otr panel LH	✓ \$25		✓	
16	Rd I rear reverse camera	✓ \$80		✓	7
17	Painting on rear floor panel	✓ \$350		✓	7/3/21
18	Painting on rear LH Sidemember	✓ \$350		✓	
19	Painting on Extension Otr panel LH	✓ \$175		✓	
20	Add on 5 day - Total: 17 day	? / SUPP			

	DATE	TAKEN BY
PHOTO BEFORE PAINT		
PHOTO AFTER PAINT		
PHOTO OF MOUNT TO CELLETTE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBAORD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: AttrageSURVEYOR: Steve - Wk

All DTCS

Ref no SM1313D
 After to Gen out Diagnostic check on electronic

2021.04.15

to Control system

to Test drive check Control

to be G.C

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition
MPI/GDI/DIESEL	KOSOSS_99880010		No DTCS	
AT/CVT/A-MT/T-C-SST	KOSOSS_99880010		No DTCS	
4WS/Electric Power Steering	KOSOSS_99880010		No DTCS	
ABS/ASC/ASTC/WSS	KOSOSS_99880010		No DTCS	
SRS-AIR BAG	KOSOSS_99880010		No DTCS	
Air Conditioner	KOSOSS_99880010		No DTCS	
ETACS	KOSOSS_99880010		No DTCS	
Meter	KOSOSS_99880010		No DTCS	
Steering Angle Sensor	KOSOSS_99880010		Non-target System	
KOS/OSS/IMMO/Keyless (with KOS)	KOSOSS_99880010		No DTCS	

Setting	
Item	Information
M.U.T.-3 Version	SEW20121-00
V.C.I. Version	B179
Vehicle Information	A13A 2021MY