

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

MITSUBISHI

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info			
AIG Asia Pacific Insurance Pte.	Cust No/Name	KCV18871/SUBRAMANIAN SENTHIL KUMAR		
Ltd.	Reg No/Reg Date	SMY3173D / 26/02/202		
MOTOR CLAIM DEPT	Date In/Mileage	22/03/2021/ 0		
78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Chassis No	MMBSTA13AMH002993		
	Engine No	3A92UJT9423		
	Make/Model	MIT/21MY ATTRAGE 1.2 CVT (E31)		
	Colour/Trim	UO1 TITANIUM GREY M/ BK BLACK		

Account No	Terms	Date/Time Printed	CSE	Operator		WIP No		
KAX00008	Credit	22/03/2021/ 13:40	6 QUK	282 / Kevin Leong		64300		
		Description of Go	ods / Service	S	Qty	Unit Price	Disc%	Amount
E PNT88000	DEAD DUM	SED DOOT END DAN						4050.00
		PER, BOOT, END PAN AFFECTED AREA	EL, LH TAIL	LAMP PANEL,				
		PARE TYRE PANEL &	DEAD DH EEN	DED				
E PNT98000	II ILLIII SI	THE THE THEE Q	NEAR KII I EN	DEK				2450.00
PAINT WO	RK ON REA	AR BUMPER, REAR BO	OT, END PAN	EL, SPARE TYRE PANEL,				2100100
	TAIL LAM	PANEL & BOTH REA	R FENDER					
E PNT88000								120.00
E PNT88000	INSTALL	REAR PARKING ASSI	ST					
	LIATONI	REAR WINDSCREEN F	OD EACTLES	TELDEDATO				240.00
M SUNDRY	INSTALL	KLAK WINDSCREEN II	OK PACILIFIA	I I I I	3			80.00
TO APPLY	WINDSCR	EN SEALANT	COT	111210111	T/C	7]		00.00
E PNT88000			0)4	1111111(31)	7/0	7		120.0
	INSTALL	REAR BOOT COMPART	MENT FOR FA	CILITATE REPAIR				
E PNT88000	TNCTALL	DEAD CEAT FOR FAO		***				120.00
M SUNDRY	INSTALL	REAR SEAT FOR FAC	ILITATE REP	AIR				100.00
	BODY SEA	ALANT ON AFFECTED	ARFA					120.00
M SUNDRY	5051 561	LANT ON ALTEOTED	MILI					80.00
PERFORM	RUST PRE	/ENTION						0010
A 13900099								450.00
	INSTALL	REAR FUEL TANK FO	R FACILITAT	E REPAIR				
A 54900099	DING & CI	HASSIS ELECTRICAL	CVCTEM					30.00
A 10028901	KING & CI	MASSIS ELECTRICAL	SISIEM					120.00
	OUT DIAG	GNOSTIC CHECK USIN	G HI-SCAN P	RO TEST				120.00
USING HI	-SCAN PRO) TEST						
M SUNDRY								50.00
TO SUPPL	Y C & C I	EMBLEM						
M SUNDRY TO SUPPL	V IMIVEC	I EMDIEM						50.00
E PNT88000	MIVEC	LI'IDLEI'I						120.00
								120.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info			
AIG Asia Pacific Insurance Pte.	Cust No/Name	KCV18871/SUBRAMANIAN SENTHIL KUMAR		
Ltd.	Reg No/Reg Date	SMY3173D / 26/02/202		
MOTOR CLAIM DEPT	Date In/Mileage	22/03/2021/ 0		
78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Chassis No	MMBSTA13AMH002993		
	Engine No	3A92UJT9423		
	Make/Model	MIT/21MY ATTRAGE 1.2 CVT (E31)		
	Colour/Trim	UO1 TITANIUM GREY M/ BK BLACK		

Account No	Terms	Date/Time Print	ted	CSE	Operator		WIP No		
KAX00008	Credit	22/03/2021/ 13	3:46	QUK	282 / Kevin Leong		64300		
		Description of	Goods /	Services		Qty	Unit Price	Disc%	Amount
	ER REAR E	BOOT COMPARTMEN	TS TO NE	W PANEL				T	
M SUNDRY									50.0
	Y REAR N	JMBER PLATE WIT	H FRAME						
M SUNDRY	V DEAD D								220.0
	Y REAR RE	EVERSE SENSOR							
M SUNDRY									50.0
SUNDRIES	MACATOO								
A WHEELALIG		F 13 10							120.0
		terize Full Whe	el Align	ment					
M REFLECTOR M LAMP ASS		DIATE		_		1.00		23.00	36.9
M LAMP ASS		PLAIE			ima	1.00		23.00	39.2
M BRACKET,			$\supset (\subset$	2771	100191	1.00	509.00		391.9
M FACE, RR		, Ln	- 17	0)11		1.00	7 654.00	23.00	21.5
M BRACKET,						1.00		23.00	503.5
M PANEL, QTI		1,111				1.00	808.00		21.5 622.1
		MP HSG,LH				1.00		23.00	46.2
		PR OTR LH				1.00	118.00	AND THE RESERVE AND THE PERSON NAMED IN COLUMN TO SERVE AND THE PERSON NAMED IN COLUMN	90.8
M PANEL, RR		N OTN EII				1.00	427.00		328.7
M STOPPER,		D GLASS				2.00		23.00	4.6
M GLASS, RR						1.00	544.00		418.88
M SPACER, RI	R WINDOW					3.00		23.00	20.7
M WEATHERS	TRIP, TRU	NK LID				1.00	157.00		120.8
M PANEL, TRI	UNK LID					1.00	795.00	E-120 To 120 To	612.1
M HINGE, TR	UNK LID,	_H				1.00	203.00	23.00	156.3
M HINGE, TR	The state of the s	RH				1.00	203.00	23.00	156.3
M LATCH, TRI						1.00	218.00	23.00	167.8
M SHIELD, RI		DUSE,LH				1.00		23.00	30.80
M MUD GUARI						1.00		23.00	26.9
M GARNISH,		ANEL				1.00	336.00	Market and Market and	258.7
M MARK, THRI						1.00		23.00	53.9
M MARK, ATTI						1.00		23.00	16.1
M TRIM, RR	END					1.00	66.00	23.00	50.8

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

MITSUBISHI

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info			
AIG Asia Pacific Insurance Pte.	Cust No/Name	KCV18871/SUBRAMANIAN SENTHIL KUMAR		
Ltd.	Reg No/Reg Date	SMY3173D / 26/02/202		
MOTOR CLAIM DEPT	Date In/Mileage	22/03/2021/ 0		
78 SHENTON WAY #09-16	Chassis No	MMBSTA13AMH002993		
AIG BUILDING SINGAPORE 079120	Engine No	3A92UJT9423		
Contact No 6419 1892	Make/Model	MIT/21MY ATTRAGE 1.2 CVT (E31)		
	Colour/Trim	UO1 TITANIUM GREY M/ BK BLACK		

Account No	Terms	Date/Time Printed	CSE	Operator		WIP No		
KAX00008	Credit	22/03/2021/ 13:46	QUK	282 / Kevin Leong		64300		
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M BOARD, TR	UNK ROOM	FLOOR			1.00	195.00	23.00	150.15



Confirm & accepted by

Nett 12,988.19 7% GST on 12988.19 909.17

Total Payable 13,897.36

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.