



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2103387

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 14/05/2021
Reference CC3/CTI21003674/Ges3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SHA 903U
Insured Veh. SLG 5845S
Claim No. SNM21D201454
Policy No. DMHCSNW00009172000
Accident Date 12/03/2021
Inspection Date 15/03/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC3/CTI21003674/Ges3q2 Date: 14/05/2021 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLG 5845S	Veh. Inspected	SHA 903U	
Policy No.	DMHCSNW00009172000	Coverage (\$)	0.00	
Claim No.	SNM21D201454	Excess (\$)	0.00	
Assign From		Assign Date	15/03/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2020	
Chassis No.	JTDKB3FU303090452	Colour	YELLOW	
Odometer	182880 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	WEST LAKE	6 mm	
L/H Front Tyre	195/65 R15	WEST LAKE	6 mm	
R/H Rear Tyre	195/65 R15	WEST LAKE	6 mm	
L/H Rear Tyre	195/65 R15	WEST LAKE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	12/03/2021	Inspection Date	15/03/2021	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 903U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	COVER REAR BUMPER	DEFORMED	499.90	499.90
1	REINFORCEMENT SUB-ASSY RE	DENTED	318.80	318.80
10	BUMPER PIECE	NECESSARY	22.00	22.00
1	GUARD REAR BUMPER CENTER	DEFORMED	552.60	552.60
1	COVER REAR BUMPER -TOW HOO	DEFORMED	82.70	82.70
1	REFLECTOR ASSY RH	NOT NECESSARY	55.00	-
1	PLATE -BACK DOOR NAME (HYBRID)	NOT NECESSARY	52.40	-
1	PANEL SUB-ASSY QUARTER RH	NOT NECESSARY	836.70	-
1	ANTENNA ELECTRICAL KEY	NECESSARY	40.48	40.48
	LESS 25% DISCOUNT		-615.15	-379.12
			1,845.43	1,137.36
	<u>SPECIAL NETT ITEMS</u>			
1	REVERSE SENSOR ASSY (SN)	NOT NECESSARY	135.70	-
1	BUMPER PROTECTOR MAT (SN)	NECESSARY	50.00	50.00
			185.70	50.00
	<u>LABOUR</u>			
	RENEW ADVERTISEMENT STICKER .		50.00	50.00
	PANEL BEATING.		900.00	350.00
	SPRAYPAINT ON AFFECTED AREA.		550.00	250.00
	TUFF COAT ON AFFECTED PARTS.	NOT NECESSARY	50.00	-
	REMOVE/REFIX UPHOLSTERY ASST REPAIR .	NOT NECESSARY	120.00	-
	REMOVE/REFIX REVERSE SENSOR .		120.00	40.00
			1,790.00	690.00
	GRAND TOTAL		3,821.13	1,877.36

RECOMMENDED COST OF REPAIRS			1,877.36
------------------------------------	--	--	-----------------

Report Ref No. CC3/CTI21003674/Ges3q2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHA 903U

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHA 903U

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHA 903U

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHA 903U

RE-INSPECTION

